

Fire Risk Assessment

17-42 Belvedere Court

Version 3

2 February 2021



Review Date: 2 February 2022

Score: Moderate Risk

Assessor: Richard Willingham

Contents

1 Action Plan Summary	3
2 Executive Summary	7
3 Introduction	9
4 Premises Details	10
5 Fire Prevention	14
6 Escape Routes & Fire Spread	17
7 Detection & Warning	21
8 Firefighting	24
9 Lighting	26
10 Signs & Notices	27
11 Fire Safety Management	29
12 Tasks	31
13 Risk Score	37

Action Plan Summary

Task No.	Category	Sub Category	Action Required	Priority	Status	Action Taken	Date Completed
1	Signs & Notices	Fire Door Signage	<p>Provide Fire Door Keep Locked Shut signs on the following doors:</p> <p>Metallic riser cupboards located in the staircase.</p>	Low	Identified		
2	Signs & Notices	Other Signage	<p>Provide signage to indicate the location of the dry riser outlet in the following locations:</p> <p>Dry riser outlets are located within lobbies, and are situated out of sight around the corner of the lobby.</p> <p>It is recommended to provide additional signage to indicate the dry risers location.</p>	Low	Identified		
3	Escape Routes & Fire Spread	Construction and Glazing	Conduct a full fire stopping survey of the building.	Medium	Identified		
4	Escape Routes & Fire Spread	Ease of Use	There are electric cables in common parts which are suspended in uPVC conduit. A requirement introduced in 2015 in BS 7671 which covers electrical installations in the UK, states that all new wiring systems are to use metal, rather than plastic, to support cables in escape routes, to prevent their premature collapse in the event of a fire.	Advisory	Identified		

5	Escape Routes & Fire Spread	Ease of Use	<p>Bikes should not be stored as to obstruct escape routes.</p> <p>A bicycle was located on the 6th floor landing.</p> <p>A bicycle and scooter was located in the 4th floor lobby.</p>	Medium	Identified
6	Escape Routes & Fire Spread	Smoke Ventilation	Remove the staircase door to the 6th floor lobby, to enable the roof-light AOV to be able to ventilate smoke from thee staircase in the event of a fire.	High	Identified
7	Escape Routes & Fire Spread	Fire Doors	Confirm that flat front doors, inspection of which was not possible, are to an FD30S self-closing standard.	Medium	Identified
8	Escape Routes & Fire Spread	Construction and Glazing	Provide fire stopping in line with the recommendations contained within the PRP report dated 24/9/20.	High	Identified
9	Detection & Warning	Automatic Fire Detection	Extend the fire detection & alarm system to provide a heat detectors and sounders in each flat to the recommendations of the National Fire Chiefs Council document entitled 'Guidance to support a temporary change to a simultaneous evacuation strategy in purpose-built flats' (third edition).	High	Identified

10	Fire Management	Procedures & Arrangements	Change to a simultaneous evacuation strategy in line with NFCC guidance while remedial works take place in relation to the recommendations within the PRP report dated 24/9/20.	High	Identified
11	Escape Routes & Fire Spread	Fire Doors	Re-hang the following doors to reduce the gaps around the doors: Staircase doors have excessive gaps in excess of 11mm	Medium	Identified
12	Detection & Warning	Automatic Fire Detection	As part of this type three fire risk assessment access was gained into flat 19 where it was noted this flat has been provided with a fire alarm to BS5839-6 LD3 standard. It is recommended that this fire alarm provision is upgraded to the recommendations of BS5839-6 LD2 D1 standard including a heat detector in the kitchen area.	Advisory	Identified
13	Fire Management	Training & Drills	It should be ensured that the waking-watch members are competent and trained in accordance with the recommendations of the National Fire Chiefs Council document entitled 'Guidance to support a temporary change to a simultaneous evacuation strategy in purpose-built flats' (third edition)	High	Identified

14	Signs & Notices	Other Signage	It is imperative that the correct fire action notice is provided (simultaneous evacuation strategy) and that all residents and visitors are informed of the change in the evacuation strategy and the action to be taken on hearing the fire alarm or discovering a fire.	High	Identified
----	-----------------	---------------	---	------	------------

15	Fire Management	Testing & Maintenance	The fire alarm system shows no evidence of testing and maintenance since May 2019. It should be tested and serviced in line with the recommendations of BS 5839-1.	High	Identified
----	-----------------	-----------------------	--	------	------------

Executive Summary

The previous FRA for this building was reviewed prior to this inspection, paying particular attention to any tasks generated by that FRA. During this inspection these tasks were inspected where access was possible, to ascertain if the recommended remedial work had been completed, and comments regarding the progress of any remedial work made accordingly.

Records for the testing and maintenance of fire safety related systems are not kept on site. These are managed centrally and are held at the ISHA Head Office.

The wall, floors and stairs in the common areas are of masonry/concrete construction.

There is a BS5839-1 fire alarm provided in the common parts of this building. This may have been provided due to concerns over compartmentation within the building. No documentation regarding the cause and effect of the system was available however, discussion with residents reveal that it may be reasonably assumed that the fire alarm provided in the common areas is not interlinked to those provided within flats. The provision of a common fire alarm system contradicts National Guidance for a building of this type (general needs, purpose built, self contained flats). A letter dated 6th January 2020 from QFSM Ltd to ISHA regarding the provision of fire alarms in common parts of blocks of flats offers guidance and recommendations on this matter and this letter should be referred to when considering whether this is a necessary provision, or if it is considered a necessary provision whether this fire alarm is of the Standard required.

NB: it is imperative that any smoke detection provided for the purpose of actuating the smoke ventilation system should remain, and it is only sounders which should be removed.

The positioning of the 6th floor lobby partition, means that the roof-light AOVs are only able to ventilate the top floor lobby, and will have no effect on the staircase where it is required. Ventilation is required for a building of this size and therefore this does not meet the minimum requirements of the building regulations at the time of construction which must have been signed off by the relevant building control body. Recommendations regarding possible solutions to remedy this matter are provided within this report.

There are cable penetrations in riser cupboards which are not fire stopped. Fire stopping installers were on site at the time of this inspection and it may be reasonably assumed that these penetrations will be properly fire stopped following their work.

There is an underground car park which is located under the whole of Belvedere Court and therefore could affect all buildings above. Tasks regarding recommended remedial work within this car park are included in the FRA for 1-16 Belvedere Court only in order to avoid duplicating tasks across three FRAs.

Giving consideration to the general fire safety arrangements within the building, and the tasks recommended as detailed within this report, it is assessed that this building presents a moderate risk. This is for the main part due to concerns over the incorrect configuration of the ventilation system.

Version 2 - 30/9/20

This review has been carried out following an invasive survey on this building by PRP Ltd. The survey included the external facade wall systems and the opening up of internal walls and ceilings within a sample of flats and the common areas.

The findings of the subsequent PRP report ref: BP9024-2-05/001 dated 24/9/20 have been considered and it is recommended that the evacuation strategy for this building is changed to Simultaneous Evacuation in line with the guidance contained within the National Fire Chiefs Council document entitled 'Guidance to support a temporary change to a simultaneous evacuation strategy in purpose-built flats' issued 1/5/18.

This should involve the introduction of a 24/7 'waking fire watch' until the common fire alarm (which is already installed in the common areas) is extended into the flats in accordance with the guidance within Appendix 2 of the NFCC document.

Consideration could also be given to the provision of a fire suppression system within the flats themselves as an alternative measure to the considerable remedial works involved with providing the appropriate internal fire stopping.

The external wall systems should be replaced or appropriately remediated following consultation with a suitably qualified chartered fire engineer.

VERSION 3:

The previous FRA for this building was reviewed prior to this inspection, paying particular attention to any tasks generated by that FRA. During this inspection these tasks were inspected where access was possible, to ascertain if the recommended remedial work had been completed, and comments regarding the progress of any remedial work made accordingly.

It was noted that there remains a number of tasks outstanding from the previous FRA which detail recommended remedial work required to ensure the safety of the building and that it is compliant with relative fire safety regulations and guidance. It is imperative that such remedial work is carried out within the recommended time frames given.

The NFCC guidance “Simultaneous evacuation guidance – guidance to support a temporary change to a simultaneous evacuation strategy in purpose-built blocks of flats” (Third Edition), p14, states that that document was written to provide guidance in response to the growing need for interim measures as a result of concerns over external wall system. It says that there may be some minor fire safety issues identified, but anything above an advisory comment in a fire risk assessment should be addressed as a matter of urgency.

ISHA instructed “PRP” to undertake a facade investigation into the building in June 2020. Following this investigation and subsequent production of a written report, it is PRP’s opinion that the external walls at Belvedere Court do not comply with the guidance in MHCLG Advice Note (Jan 2020) and therefore remediation is required.

Projecting balconies observed at Belvedere Court are in a stacked arrangement. The primary structure is steel and secondary structure is timber with timber decking. In PRP’s opinion these pose a fire risk and should be remediated.

Due the external walls being constructed of timber frame advice from a Chartered Fire Engineer should be sought to support and agree any remediation proposals.

PRP also recommended that any required interim measures should be considered and implemented to mitigate the risk of fire and fire spread as well as resident safety.

The findings by PRP following the intrusive investigation and the recommendations of the report support a temporary change to a simultaneous evacuation strategy in this building and interim measures should be put in place which meets the recommendations of the NFCC guidance “Simultaneous evacuation guidance – guidance to support a temporary change to a simultaneous evacuation strategy in purpose-built blocks of flats” (Third Edition)

Some interim measures have already been put in place such as the provision of a 24/7 waking-watch patrol, who patrol the whole of the building at regular intervals.

It should be confirmed that the waking-watch personnel meet the waking-watch person specification as detailed in Appendix 4 of the NFCC guidance. Waking-watch personnel should be competent in carrying out an evacuation management role as detailed in Appendix 5 of that guidance.

Following access into flats and discussion with the residents it is evident that no change has been made to the common fire alarm provided in the building. The purpose of the provision of a common fire alarm to support the change of the evacuation strategy from stay put to simultaneous evacuation is to ensure early detection and warning of a fire throughout the building (including any accommodation e.g. individual flats). The current original common fire alarm is not interlinked into flats and therefore does not meet this requirement. The fire alarm provision throughout the building should be reviewed and it is recommended that it is upgraded to meet the recommendations of Appendix 2 of the NFCC guidance.

PRP also carried out intrusive investigations within flats. This investigative work also highlighted concerns regarding service penetrations in the building and lack of adequate fire stopping. It is PRPs opinion that all service penetrations should be adequately fire stopped with coated mineral wool fire batt and compatible sealant. The junction between the wall and sealant should also be adequately sealed.

Introduction

This report presents the significant findings of a fire risk assessment carried-out at the premises by QFSM Ltd. The scope, format and limitations of the fire risk assessment have been discussed and agreed with the client.

The scope of the assessment does not include individual dwellings. Notwithstanding any statement or recommendation made with respect to smoke/heat alarms within dwellings, it is always recommended as best practice to ensure that working smoke alarms are provided in all dwellings at least to a BS 5839-6 Category LD3 standard. These should ideally be Grade D alarms (mains powered with integral battery back-up), although Grade F alarms (battery powered only) are a reasonable short term measure.

The report includes an action plan which contains recommended tasks, each with a suggested due date. These due dates are only our suggestions, and may or may not be appropriate, depending on individual circumstances such as financial constraints and requirements of enforcing authorities.

The premises risk score was assessed at the time of the fire risk assessment, and a recommended review date has been provided. The actual level of risk may change over time, as a result of tasks being completed, or new risks arising. Regardless of the review date, the fire risk assessment should be reviewed regularly so as to keep it up to date and particularly if:

- there is reason to suspect that the fire risk assessment is no longer valid; or
- there has been a significant change in the matters to which the fire risk assessment relates.

If you have any queries please contact QFSM Ltd at office@qfsm ltd.co.uk.

Premises Details

Building Information

Address line 1	17-42 Belvedere Court
Address line 2	De Beauvoir Crescent
Town	Hackney
Postcode	N1 5SG
FRA Type	Type 1 - Common parts only (non-destructive)
Description	<p>A Type 1 fire risk assessment has been conducted at this building. This means the inspection of the building has been non-destructive. As well as considering the arrangements for means of escape, the fire risk assessment has included, where possible, the examination of a sample of flat entrance doors. It has also considered, so far as reasonably practicable, the separating construction between the flats and the common parts without any intrusive examination of construction. This Type of fire risk assessment has not involved entry to flats beyond the area of the flat entrance door.</p>
Client	ISHA
Use	Purpose-built, self-contained flats
Number of floors - ground and above	7
Number of floors - below ground	1
Number of flats	26
Number of stair cores	1

Approach to flats

- Direct from stair
- Via protected lobbies / corridors

Approximate period of construction

2000-2010

Is the top occupied storey over 18 metres above access level?

Yes

Is the external cladding or facade confirmed as non combustible?

Not Known

Further details

Building of seven floors with an underground car park.

Single staircase - Flats are accessed via protected corridors.

Construction details

Steel frame construction with brick & render infill, intermediate concrete floors and a flat roof.

Access to common area via secure door entry system at front elevation, with flats accessed from protected lobbies at each floor.

Passenger lift provided at each floor level.

Gas & electric riser cupboards at each floor.

Dry Riser inlet located at front elevation, with outlets in lobbies at each floor level above.

There is an underground car park which is located under the whole of Belvedere Court and therefore could affect all buildings above. Tasks regarding recommended remedial work within this car park are included in the FRA for 1-16 Belvedere Court only in order to avoid duplicating tasks across three FRAs.



External walls end rear elevation



Timber cladding on sixth floor



External walls-front elevation



Configuration and construction of common balconies.



Timber cladding within inset (Juliet) balconies

External wall details

An intrusive investigation into the external walls of this building was carried out by PRP in June 2020, with a second visit to carry out internal investigations within flats in August 2020. A report dated the 24th of September 2020 was produced (ref BP9024-2-05/001)

The findings detailed within the PRP report indicates there are 3 main external wall constructions that were considered; these were terracotta block, timber cladding and EWI / Render on insulation fixed directly to the timber frame infill walling.

The report summarises the findings and recommendations as follows:

Terracotta Block:

In PRP's opinion the terracotta blockwork wall types require no remediation. This is should be confirmed with a Chartered Fire Engineer.

Timber Cladding:

Timber cladding, battens, foil insulation and sheathing board should be removed. The remaining timber studs and mineral wool insulation should be encapsulated with a minimum A2, s1-d0 rated sheathing board, aluminium support system and minimum A2, s1-d0 rated cladding. Siderise cavity barriers or similar barriers should be installed at compartment walls, floors and around openings including service penetrations.

EPS Insulation:

In PRP's opinion the render, EPS insulation, timber sheathing board and timber battens should be removed. The existing timber studs and mineral wool insulation should be encapsulated with a minimum A2, s1-d0 rated sheathing board, mineral wool insulation and render finish. Cavity barriers should be installed in accordance with the render system manufacturers requirements and AD B B3 Vol. 1 2019

Attention is drawn to the Ministry of Housing, Communities & Local Government Consolidated Advice Note for building owners of multi-storey, multi-occupied residential buildings, dated January 2020.

The Advice Note recommends that building owners should consider the risk of external fire spread as part of the fire risk assessment for multi-occupied residential buildings. Consideration has been given to this matter within this fire risk assessment. The Advice Note further recommends the assessment of the fire risks of any external wall system, irrespective of the height of the building.

Are there any private balconies?

Yes

Private balcony details

Balconies observed were constructed from structural steel with timber decking and handrail, the balustrading is a combination of steel and glass. Whether the glass is toughened or laminated or both still needs to be confirmed. The balconies are installed in a stacked arrangement. In PRP's opinion the timber decking and timber secondary support structure should be replaced with LWSF secondary support structure and MyDek or equal and approved A2, s1-d0 rated decking.

In the interim, residents should be advised about the risks arising from the presence of combustible materials on private balconies. They should make clear that smoking, the use of barbecues and storage of flammable property on balconies can increase that risk. Advice from fire and rescue authorities is also clear that barbecues should not be used on balconies (MHCLG Advice Note on Balconies on Residential Buildings, June 2019)

People

Are there any people especially at risk from fire?

Not Known

Fire Prevention

Electrical

Are electrical installations and appliances free from any obvious defect?

Yes

Are fixed installations periodically inspected and tested?

Yes

Are portable electrical appliances used?

No

Comments

Documentation regarding the testing and maintenance of fixed electrical installations is held centrally by ISHA. The Neighbourhood Officer has confirmed these are all up to date.

There are electrical sockets in the common areas, presumably for use by cleaning staff. These were in good condition and showed no evidence of misuse by residents or visitors.

There are electric cables in common parts which are suspended in uPVC conduit. A requirement introduced in 2015 in BS 7671 which covers electrical installations in the UK, states that all new wiring systems are to use metal, rather than plastic, to support cables in escape routes, to prevent their premature collapse in the event of a fire.

Gas

Are gas installations and appliances free from any obvious defect?

Yes

Is gas equipment protected/located so as not to be prone to accidental damage?

Yes

Comments

There are gas vents located in common corridors. It is unusual to find these vents in common escape routes and it is recommended to consult a qualified gas engineer to see if this is acceptable within relevant gas regulations.



Gas vents in common corridors

Heating

Are fixed heating installations free from any obvious defect?

N/A

Are portable heaters used?

No

Comments

There is no heating provision in the common areas.

Cooking

Does cooking take place on the premises?

No

Comments

Cooking takes place within flats only and does not take place in the common parts.

Arson

Is security against arson reasonable?

Yes

Is there a reasonable absence of external fuels and ignition sources?

Yes

Comments

Access was gained into this building via a secured main entrance door.

CCTV cameras are installed internally and externally. Whilst these cameras may have been installed for security purposes they also serve to reduce the risk of deliberate fire setting.

The externally accessed bin store was found locked and secured.



The externally accessed bin store was found locked and secured.

Housekeeping

Is accumulation of combustibles or waste avoided?

Yes

Are there appropriate storage facilities for combustible & hazardous materials?

N/A

Comments

All common areas appeared clean, tidy and free of combustible items.

Building Works

Are there any hot works being carried-out at this time?

No

Are the premises free of any obvious signs of incorrect hot work procedures in the past?

Yes

Smoking

Are there suitable arrangements taken to prevent fires caused by smoking?

Yes

Comments

“No Smoking” signage is provided, and there is no evidence of smoking taking place in the common parts.

Dangerous Substances

Are dangerous substances present, or liable to be present?

No

Lightning

Is a lightning protection system installed?

Not Known

Comments

There is no lightning protection visible, However, if there is lightning protection in place it should be periodically inspected by a competent person, to the frequency recommended in BS EN 62305.

Escape Routes & Fire Spread

Ease of Use

Are exits easily and immediately openable?

Yes

Do fire exits open in direction of escape where necessary?

N/A

Are escape routes unobstructed and safe to use?

No

Are there reasonable measures for the evacuation of disabled people?

Yes

Comments

There are electric cables in common parts which are suspended in uPVC conduit. A requirement introduced in 2015 in BS 7671 which covers electrical installations in the UK, states that all new wiring systems are to use metal, rather than plastic, to support cables in escape routes, to prevent their premature collapse in the event of a fire.

A bicycle was located on the 6th floor landing.

A bicycle and scooter was located in the 4th floor lobby.

Dimensions

Are travel distances reasonable?

Yes

Is there sufficient exit capacity?

Yes

Fire Doors

Doors which are expected to be fire resisting:

- Flats
- Risers

Flat Doors

- FD30S self-closing

Riser Doors

- FD30S

Are fire doors to a suitable standard?

Yes

Is there suitable provision of self-closing devices?

Yes

Is there suitable provision of hold-open devices?

N/A

Are doors kept locked where appropriate?

Yes

Comments

As part of this Fire Risk Assessment, access was gained into a sample flat to assess the suitability of flat entrance doors, and any internal doors which open onto the entrance hallway.

Access was gained into flat 37 which has an entrance door fitted to FD30S SC standard, and the internal doors which open onto the entrance hallway are fire resisting.

The remainder of flat front doors within the building could not be assessed due to access. However, these all appear to be of the same age, condition and design of those which were accessed and were probably all installed at the same time. It is therefore reasonable to assume that they are of the same fire resisting standard.

The provision and condition of self closing devices, intumescent strips/cold smoke seals, and effective door closing action of these doors however could not be assessed and this should be confirmed ensure all doors afford FD30S SC standard of fire resistance.

VERSION 3:

As part of the site investigations on the 11th of August 2020 PRP also inspected a sample of flat entrance doors. It was their conclusions that the inspected doors were 40 mm thick and therefore it is assumed they are FD30 doors. Doors were functioning with overhead door closes and intumescent smoke seals. PRP state however, that the door frames were either not fire stopped within the aperture or the gap was filled with PU expanding foam. This should be remedied as per the recommendations of the PRP report.

Construction & Glazing

Are escape routes protected with suitable walls and floors?

Yes

Is there adequate compartmentation?

No

Is there reasonable limitation of linings that might promote fire spread?

Yes

Glazing which is expected to be fire resisting, inc vision panels and fanlights:

• Lobbies

Lobby Glazing

• 30 mins E

Is glazing reasonable and free from any obvious defects?

Yes


Comments

There is a basement carpark underneath the whole of Belvedere Court. Highlighted issues and recommended remedial work within the carpark is captured within the fire risk assessment for 1 to 16 Belvedere Court

A programme of fire stopping has been carried out by “Carringtons” in June 2019, however following intrusive examination by PRP they note that service penetrations within both the communal corridor ceiling and within the dwelling ceilings were not fire stopped it is PRPs opinion that all service penetrations should be adequately fire stopped with coated mineral wool fire bat and compatible sealants. The junction between the walls and ceilings should also be adequately sealed.



Acid etching on “Pyroguard” FR Glazed lobbies.



Example of Fire stopping certification label in risers



Fire stopping in risers

Dampers, Ducts & Chutes

Are there suitable measures to restrict fire spread via ducts and concealed spaces?

Yes

Comments

No Dampers, Ducts or Chutes evident.

Smoke Ventilation

Areas where smoke ventilation is expected:

- Staircases

Staircases

- Openable Windows
- Natural Vent - Automatic

Is smoke ventilation reasonable and free from any obvious defects?

No

Comments

The positioning of the 6th floor lobby partition, means that the roof-light AOVs are only able to ventilate the top floor lobby, and will have no effect on the staircase where it is required.

Ventilation is required for a building of this size and therefore this does not meet the minimum requirements of the building regulations at the time of construction which must have been signed off by the relative building control body.

Repositioning the roof-light AOVs is not a reasonably practicable solution. However, removing the staircase door from the top floor lobby would allow the AOVs to have their desired effect on removing smoke from the staircase.

This would have some minimal impact on the protection of the staircase at the top floor, however, this would only be affected if there is a fire in any off the 6th floor flats. Should a fire occur on the 6th floor, the AOV would actuate and is located in the immediate area of these flats and would therefore ventilate the and products of combustion away from the 6th floor.



AOV located in 6th floor lobby.



Partition compromising staircase AOV.

Detection & Warning

Control Equipment

Is an electrical fire alarm system expected?

No

Why not?

Purpose-built flats

Is a fire detection and/or alarm system provided?

Yes

Areas covered

- Communal areas

Communal Areas

System Category

- BS 5839 Pt1 Category L5

Cause & Effect

- Sounds alarm in communal areas
- Operates smoke ventilation

Is the control equipment suitably located?

Yes

Is the control equipment free from any obvious fault or defect?

Yes



Fire alarm control panel

Manual Fire Alarms

Are there sufficient means of manually raising an alarm?

No

Are manual callpoints appropriately located and free from obvious defect?

Yes

Comments

There are fire alarm manual call-points provided in the common parts of this building.

A letter dated 6th January 2020 from QFSM Ltd to ISHA regarding the provision of fire alarms in common parts of blocks of flats offers guidance and recommendations on this matter and this letter should be referred to when considering whether this is a necessary provision, or if it is considered a necessary provision whether this fire alarm is of the Standard required.

Version 2

The manual call points should remain in the common areas until the remedial work has been carried out.

VERSION 3:

Following access into flats and discussion with the residents it is evident that no change has been made to the common fire alarm provided in the building. The purpose of the provision of a common fire alarm to support the change of the evacuation strategy from stay put to simultaneous evacuation is to ensure early detection and warning of a fire throughout the building (including any accommodation e.g. individual flats). The current original common fire alarm is not interlinked into flats and therefore does not meet this requirement. The fire alarm provision throughout the building should be reviewed and it is recommended that it is upgraded to meet the recommendations of Appendix 2 of the NFCC guidance.

Automatic Fire Detection

Is there sufficient provision of automatic fire detection?

No

Is the type of automatic fire detection suitable and free from obvious defect?

Minor Defects

Comments

Due to design and construction issues highlighted following an intrusive examination of the building it has been deemed necessary to temporarily move to a simultaneous evacuation strategy in this building.

Documentation regarding the cause and effect of fire alarms provided in the building was not available. Discussion with residents could not confirm whether common fire alarm extends into flats. Visual examination of fire alarms within flats shows that this is unlikely.

The cause and affect of the current provided fire alarm both in common areas and within flats should be reviewed in order to ensure that it meets the recommendations of the National Fire Chiefs Council document entitled 'Guidance to support a temporary change to a simultaneous evacuation strategy in purpose-built flats' (third edition).

As part of this type three fire risk assessment access was gained into flat 19 where it was noted this flat has been provided with a fire alarm to BS5839-6 LD3 standard. It is recommended that this fire alarm provision is upgraded to the recommendations of BS5839-6 LD2 D1 standard including a heat detector in the kitchen area.

Audibility

Are there adequate means of alerting all relevant persons?

No

Comments

Please see task generated in “automatic fire detection” section of this report.

Firefighting

Fire Extinguishers

Are fire extinguishers expected?

No

Why not?

- Not practicable to train residents
- Fire unlikely in communal areas
- Vandalism concerns

Are fire extinguishers provided?

No

Is the provision of fire extinguishers reasonable?

Yes

Comments

Fire extinguishers are not required or desirable in the common areas of a purpose built, general needs block of flats as flat occupants would not necessarily be trained in their use and limitations. Furthermore there is no expectation that flat occupants would leave a fire in their flat to retrieve an extinguisher and then return to fight the fire, since it is likely to have developed significantly in their absence.

Fixed Systems

Are any fixed systems provided?

No

Is provision of fixed systems reasonable?

Yes

Fire Service Facilities

Are any fire service facilities provided?

Yes

Types of facility

- Dry rising main
- Smoke ventilation
- Premises information box

Is provision of fire service facilities reasonable?

Yes

Comments

It was not possible to access the premises information box to inspect contents.



Floor numbers are clearly identified.

Lighting

Normal Lighting

Is there adequate lighting of internal escape routes?

Yes

Is there adequate lighting of external escape routes?

Yes

Is there adequate lighting in risk critical areas?

Yes

Emergency Lighting

Method of emergency lighting of internal escape routes:

- Borrowed light
- Maintained emergency lighting (local)

Is this provision reasonable?

Yes

Method of emergency lighting of external escape routes:

- Borrowed light
- Maintained emergency lighting (local)

Is this provision reasonable?

Yes

Method of emergency lighting of other areas:

- None
- Maintained emergency lighting (local)

Is this provision reasonable?

Yes

Comments

Although this inspection took place during daylight hours, given the provision of street lighting in the immediate vicinity and lighting provided by surrounding buildings, it is reasonable to assume there would be sufficient borrowed light to aid escape in these areas.

Signs & Notices

Escape Routes

Is escape route signage necessary?

Yes

Is escape route signage provided?

Yes

Is provision of escape route signage suitable?

Yes

Fire Doors

Is there signage suitable for self-closing fire doors?

Yes

Is there signage suitable for locked fire doors?

Minor Defects

Is there signage suitable for automatic fire doors?

N/A

Comments

Provide Fire Door Keep Locked Shut signs on the Metallic riser cupboards located in the staircase

Other Signs & Notices

Is there suitable signage for fire service facilities?

Minor Defects

Are fire action notices suitable?

No

Are there suitable notices for fire extinguishers?

N/A

Is there suitable zone information for the fire alarm system?

Yes

Comments

Dry riser outlets are located within lobbies, and are situated out of sight around the corner of the lobby.

It is recommended to provide additional signage to indicate the dry risers location.

As stated previously in this report there has been a move to a simultaneous evacuation strategy in this building, however the fire action notice remains for a stay put strategy.

Discussion with residents revealed that they are not clear on the move to a simultaneous evacuation strategy and were unsure as to the cause and effect of the fire alarm and the action I should take.

It is imperative that the correct fire action notice is provided (simultaneous evacuation strategy) and that all residents and visitors are informed of the change in the evacuation strategy and the action to be taken on hearing the fire alarm or discovering a fire.

Fire Safety Management

Procedures & Arrangements

Current evacuation policy

Simultaneous

Further details

There is a temporary move to a simultaneous evacuation strategy in the building until remedial work regarding the external walls has been completed. As previously stated within this report it should be confirmed that these interim measures meet the recommendations of the National Fire Chiefs Council document entitled 'Guidance to support a temporary change to a simultaneous evacuation strategy in purpose-built flats' (third edition), in order to ensure that the interim measures are sufficient to fully support a temporary move to a simultaneous evacuation strategy.

Are fire action procedures suitable and appropriately documented?

No

Are there suitable arrangements for calling the fire service?

N/A

Is there a suitable fire assembly point?

N/A

Are there suitable arrangements for the evacuation of disabled people?

Yes

Comments

These are general needs flats and as such no specific occupancy risk is identified. Tenants are presumed to be a typical cross section of public and could include visitors and contractors. It is assumed that all occupants and visitors are capable of using the means of escape unaided to reach a place of ultimate safety, however it should be encouraged to start building a list of residents and their individual needs, and start putting in place arrangements to keep the information up to date.

Training & Drills

Are staff regularly on the premises?

No

Are employees from outside organisations given appropriate fire safety information?

Yes

Comments

Fire Action notices provide sufficient information to inform persons from outside organisations of the action to take in the event of a fire alarm actuation or discovering a fire.

It should be ensured that the waking-watch members are competent and trained in accordance with the recommendations of the National Fire Chiefs Council document entitled 'Guidance to support a temporary change to a simultaneous evacuation strategy in purpose-built flats' (third edition)

Testing & Maintenance

Was testing & maintenance information available?

No

Are fire extinguishers subject to suitable test & maintenance?

N/A

Comments

Fire Safety documentation for the testing and maintenance of fire safety systems is held centrally at the ISHA Head Office. The ISHA Neighbourhood Officer has confirmed that these are up to date.

However, the fire alarm system shows no evidence of testing and maintenance since May 2019. It should be tested and serviced in line with the recommendations of BS 5839-1.

Record Keeping

Were fire safety records available?

No

Comments

Fire Safety documentation for the testing and maintenance of fire safety systems is held centrally at the ISHA Head Office. The ISHA Neighbourhood Officer has confirmed that these are up to date.

Tasks

Task 1

Source Version	1
Category	Signs & Notices
Sub Category	Fire Door Signage
Action Required	Provide Fire Door Keep Locked Shut signs on the following doors: Metallic riser cupboards located in the staircase.
Priority	Low
Status	Identified
Owner	Neighbourhood Services
Due Date	6 March 2021



Task 2

Source Version	1
Category	Signs & Notices
Sub Category	Other Signage
Action Required	Provide signage to indicate the location of the dry riser outlet in the following locations: Dry riser outlets are located within lobbies, and are situated out of sight around the corner of the lobby. It is recommended to provide additional signage to indicate the dry risers location.
Priority	Low
Status	Identified
Due Date	6 March 2021



Task 3

Source Version	1
Category	Escape Routes & Fire Spread
Sub Category	Construction and Glazing
Action Required	Conduct a full fire stopping survey of the building.
Priority	Medium
Status	Identified
Due Date	4 September 2020

Task 4

Source Version	1
Category	Escape Routes & Fire Spread
Sub Category	Ease of Use
Action Required	There are electric cables in common parts which are suspended in uPVC conduit. A requirement introduced in 2015 in BS 7671 which covers electrical installations in the UK, states that all new wiring systems are to use metal, rather than plastic, to support cables in escape routes, to prevent their premature collapse in the event of a fire.
Priority	Advisory
Status	Identified
Due Date	6 March 2022


Task 5

Source Version	1
Category	Escape Routes & Fire Spread
Sub Category	Ease of Use
Action Required	Bikes should not be stored as to obstruct escape routes. A bicycle was located on the 6th floor landing. A bicycle and scooter was located in the 4th floor lobby.
Priority	Medium
Status	Identified
Due Date	4 September 2020



Task 6

Source Version	1
Category	Escape Routes & Fire Spread
Sub Category	Smoke Ventilation
Action Required	Remove the staircase door to the 6th floor lobby, to enable the roof-light AOV to be able to ventilate smoke from the staircase in the event of a fire.
Priority	High
Status	Identified
Due Date	4 June 2020



Task 7

Source Version	1
Category	Escape Routes & Fire Spread
Sub Category	Fire Doors
Action Required	Confirm that flat front doors, inspection of which was not possible, are to an FD30S self-closing standard.
Priority	Medium
Status	Identified
Due Date	4 September 2020

Task 8

Source Version	2
Category	Escape Routes & Fire Spread
Sub Category	Construction and Glazing
Action Required	Provide fire stopping in line with the recommendations contained within the PRP report dated 24/9/20.
Priority	High
Status	Identified
Owner	Customer Homes
Due Date	28 December 2020

Task 9

Source Version	2
Category	Detection & Warning
Sub Category	Automatic Fire Detection
Action Required	Extend the fire detection & alarm system to provide a heat detectors and sounders in each flat to the recommendations of the National Fire Chiefs Council document entitled 'Guidance to support a temporary change to a simultaneous evacuation strategy in purpose-built flats' (third edition).
Priority	High
Status	Identified
Owner	Customer Homes
Due Date	28 December 2020

Task 10

Source Version	2
Category	Fire Management
Sub Category	Procedures & Arrangements
Action Required	Change to a simultaneous evacuation strategy in line with NFCC guidance while remedial works take place in relation to the recommendations within the PRP report dated 24/9/20.
Priority	High
Status	Identified
Owner	Customer Homes
Due Date	28 December 2020

Task 11

Source Version	3
Category	Escape Routes & Fire Spread
Sub Category	Fire Doors
Action Required	Re-hang the following doors to reduce the gaps around the doors: Staircase doors have excessive gaps in excess of 11mm
Priority	Medium
Status	Identified
Owner	Customer Homes
Due Date	3 August 2021



Task 12

Source Version	3
Category	Detection & Warning
Sub Category	Automatic Fire Detection
Action Required	As part of this type three fire risk assessment access was gained into flat 19 where it was noted this flat has been provided with a fire alarm to BS5839-6 LD3 standard. It is recommended that this fire alarm provision is upgraded to the recommendations of BS5839-6 LD2 D1 standard including a heat detector in the kitchen area.
Priority	Advisory
Status	Identified
Owner	Customer Homes
Due Date	2 February 2023

Task 13

Source Version	3
Category	Fire Management
Sub Category	Training & Drills
Action Required	It should be ensured that the waking-watch members are competent and trained in accordance with the recommendations of the National Fire Chiefs Council document entitled 'Guidance to support a temporary change to a simultaneous evacuation strategy in purpose-built flats' (third edition)
Priority	High
Status	Identified
Owner	Neighbourhood Services
Due Date	3 May 2021

Task 14

Source Version	3
Category	Signs & Notices
Sub Category	Other Signage
Action Required	It is imperative that the correct fire action notice is provided (simultaneous evacuation strategy) and that all residents and visitors are informed of the change in the evacuation strategy and the action to be taken on hearing the fire alarm or discovering a fire.
Priority	High
Status	Identified
Owner	Neighbourhood Services
Due Date	3 May 2021

Task 15

Source Version	3
Category	Fire Management
Sub Category	Testing & Maintenance
Action Required	The fire alarm system shows no evidence of testing and maintenance since May 2019. It should be tested and serviced in line with the recommendations of BS 5839-1.
Priority	High
Status	Identified
Owner	Neighbourhood Services
Due Date	3 May 2021



Risk Score

Risk Score

Moderate Risk

Next Assessment Due

2 February 2022

Likelihood	Potential Consequence		
	Slight Harm	Moderate Harm	Extreme Harm
High	Moderate	Substantial	Intolerable
Medium	Tolerable	Moderate	Substantial
Low	Trivial	Tolerable	Moderate

Likelihood

- Low** Unusually low likelihood of fire as a result of negligible potential sources of ignition.
- Medium** Normal fire hazards (e.g. potential ignition sources) for this type of occupancy, with fire hazards generally subject to appropriate controls (other than minor shortcomings).
- High** Lack of adequate controls applied to one or more significant fire hazards, such as to result in significant increase in likelihood of fire.

Consequence

- Slight** Outbreak of fire unlikely to result in serious injury or death of any occupant (other than an occupant sleeping in a room in which a fire occurs).
- Moderate** Outbreak of fire could foreseeably result in injury (including serious injury) of one or more occupants, but it is unlikely to involve multiple fatalities.
- Extreme** Significant potential for serious injury or death of one or more occupants.