


Fire Risk Assessment 92-94 Graham Rd Version 5

22 August 2023



Review Date: 22 August 2024 Score: Moderate Risk Assessor: Andy Harris

Contents

1 Action Plan Summary	
2 Introduction	
3 Executive Summary	
4 Premises Details	
5 Fire Prevention	
6 Escape Routes & Fire Spread	
7 Detection & Warning	
8 Firefighting	
9 Lighting	
10 Signs & Notices	
11 Fire Safety Management	
12 Tasks	
13 Risk Score	

Action Plan Summary

Task No	. Category	Sub Category	Action Required	Priority	Status	Action Taken	Date Completed
1	Escape Routes & Fire Spread	Ease of Use	Bikes should not be stored as to obstruct escape routes. This has been identified in previous FRAs 22/08/23 This task is still outstanding.	Medium	Identified		
2	Signs & Notices	Escape Route Signage	Provide escape signage on lobby door on the ground floor. It is indistinguishable from the adjacent flat entrance doors and therefore should be clearly identified as the escape route for escaping persons in the event of a fire. 22/08/23 This task is still outstanding	Medium	Identified		

3	Escape Routes & Fire Spread	Smoke Ventilation	The roof vent at the head of the stairs was found to be open at the time of this inspection. This has probable been opened via a manual vent actuator by a resident. These were found to be insecure and require repair/replacement to ensure this fire safety system is not abused. VERSION 4: This vent was closed at the time of this inspection, however, the "break glass" cover over the smoke vent control in the entrance hallway still requires repair to prevent future misuse. 22/08/23 The roof vent at the head of the stairs was found to be closed but the break "glass cover" still requires repair so this task is still outstanding.	Low	Identified
4	Escape Routes & Fire Spread	Construction and Glazing	Given the presence of other services being carried through the building common areas such as water, without fire stopping installed, it is recommended that a full compartmentation survey is carried out in this building	Advisory	Identified
			22/08/23 This task is still outstanding		

5	Escape Routes & Fire Spread	Construction and Glazing	Provide fire stopping around cable penetrations in the following locations:	Medium	Identified
			It is evident in the electrical cupboard there are numerous penetrations which are not fire stopped. The cabling appears to be carried through the building via boxed-in sections, and it cannot be confirmed if these are fire stopped where they enter flats. These penetrations should be fire stopped within the electrical cupboard.		
			NB: This has been identified in previous FRAs		
			22/08/23 This task is still outstanding		

6	Signs & Notices	Other Signage	 Provide fire action notice Provide fire action notices which accurately reflects the evacuation policy in place and confirm the correct action to take in the event of fire. The fire action notice provided gives instruction for a simultaneous evacuation policy and not a stay put policy which is the correct policy for this building. s which confirm the action to take in the event of fire. NB: This has been identified in previous FRAs 22/08/23 This task is still outstanding 	Medium	Identified
7	Fire Management	Training & Drills	It should be ensured that employees from outside organisations are given information on the action to take in the event of fire. Note - the current fire action notice is incorrect. NB: This has been identified in previous FRAs 22/08/23 This task is still outstanding	Medium	Identified

Escape Routes & Fire Doors Fire Spread

8

Confirm that flat front doors, inspection of which was not possible, are to an FD30S self-closing standard.

Flat entrance doors within the building could not be assessed due to access. However, these all appear to be of the same age, condition and design and were probably installed at the same time. The doors appear to be solid with at least 25mm door stops. There are externally fitted self closing devices fitted to all doors, which all appear to be in good condition, are connected to the doors with no visible damage.

The provision and condition of intumescent strips/cold smoke seals, and effective door closing action of these doors however could not be assessed and this should be confirmed ensure all doors afford FD30S SC standard of fire resistance.

22/08/23

It was not possible to gain access to any entrance door to flats so this task is still outstanding Identified

Low

9	Escape Routes & Fire Spread	Fire Doors	The following doors should be kept locked shut: Electrical cupboard. NB: This has been identified in previous FRAs 22/08/23 This task is still outstanding	Low	Identified
10	Escape Routes & Fire Spread	Fire Doors	Install intumescent strips and smoke seals on the following doors: Electrical cupboard, lower ground floor. NB: This has been identified in previous FRAs 22/08/23 This task is still outstanding	Medium	Identified
11	Signs & Notices	Fire Door Signage	 Provide Fire Door Keep Locked Shut signs on the following doors: Electrical cupboard, lower ground floor. NB: This has been identified in previous FRAs 22/08/23 This task is still outstanding 	Low	Identified

Introduction

This report presents the significant findings of a fire risk assessment carried-out at the premises by QFSM Ltd. The scope, format and limitations of the fire risk assessment have been discussed and agreed with the client.

The scope of the assessment does not include individual dwellings. Notwithstanding any statement or recommendation made with respect to smoke/heat alarms within dwellings, it is always recommended as best practice to ensure that working smoke alarms are provided in all dwellings at least to a BS 5839-6 Category LD3 standard. These should ideally be Grade D alarms (mains powered with integral battery back-up), although Grade F alarms (battery powered only) are a reasonable short term measure.

The report includes an action plan which contains recommended tasks, each with a suggested due date. These due dates are only our suggestions, and may or may not be appropriate, depending on individual circumstances such as financial constraints and requirements of enforcing authorities.

The premises risk score was assessed at the time of the fire risk assessment, and a recommended review date has been provided. The actual level of risk may change over time, as a result of tasks being completed, or new risks arising. Regardless of the review date, the fire risk assessment should be reviewed regularly so as to keep it up to date and particularly if:

• there is reason to suspect that the fire risk assessment is no longer valid; or

• there has been a significant change in the matters to which the fire risk assessment relates.

If you have any queries please contact QFSM Ltd at office@qfsmltd.co.uk.

Executive Summary

Records for the testing and maintenance of fire safety related systems are not kept on site. These are managed centrally and are held at the ISHA Head Office.

Tasks generated by the previous FRA conducted in 2018 were checked to ascertain if the recommended remedial work had been completed. None of these tasks have been completed and therefore these remain as "identified"

Attempts were made at each flat in the building to gain access to asses the provision and suitability of flat entrance doors regarding their fire resisting standard, and to assess the provision and suitability of any fire alarm provided within flats, however, this was not possible.

Flat entrance doors within the building all appear to be of the same age, condition and design and were probably installed at the same time. The doors appear to be solid with at least 25mm door stops. There are externally fitted self closing devices fitted to all doors, which all appear to be in good condition, are connected to the doors with no visible damage.

VERSION 3:

There are cable penetrations in the electrical cupboard which are not fire stopped and given the presence of other services being carried through the building common areas such as water and electrics, without fire stopping installed, it is recommended that a full compartmentation survey is carried out in this building, to ensure there is adequate fire separation to support a stay put policy.

There are bikes being stored on the escape route. These are positioned on the stairs themselves and would cause a major obstruction to escaping persons in the event of a fire and should be removed. There is also a large quantity of combustible items on the top floor landing.

Giving consideration to the general fire safety arrangements within the building, and the tasks required as detailed within this report, it is assessed that this building presents a tolerable risk.

VERSION 3:

It is evident that none of the recommended remedial work from the previous FRAs has been completed and the building was noted as being in much the same condition with regard to the management of fire safety as it was in previous FRAs. It is imperative that recommended remedial work is carried out in order that residents and visitors in the building remains safe from fire and the building complies with th RRO and relevant guidance.

VERSION 4:

It is again noted that there remains a number of tasks outstanding from the previous FRA which detail recommended remedial work required to ensure the safety of the building and that it is compliant with relative fire safety regulations and guidance. It is evident that the fire safety measures and overall fire safety of this building has not been improved at all since the last FRA conducted in 2020, nor indeed since any FRAs conducted in previous years. In summary, no task identified in the previous FRA has been completed, which includes defects identified to the smoke ventilation system, fire alarm defects within flats and fire stopping concerns.

It is imperative that recommended remedial work is carried out within the recommended time frames given.

This new version was created on 22/08/2023 and is not a review of the fire risk assessment. This is purely an on-site audit carried out at the request of the client to ascertain the progress of any action carried out against previous tasks identified in previous versions of this fire risk assessment.

This new version was created on 22/08/2023 and is not a review of the fire risk assessment. This is purely an on-site audit carried out at the request of the client to ascertain the progress of any action carried out against previous tasks identified in previous versions of this fire risk assessment.

Premises Details

Building Information

Address line 1	92-94 Graham Road
Town	Hackney
Postcode	E8 1BX
FRA Type	Type 3 – Common parts and flats (non- destructive)

Description

A Type 3 fire risk assessment includes the work involved in a Type 1 fire risk assessment, but goes beyond the scope of the FSO (though not the scope of the Housing Act). This risk assessment considers the arrangements for means of escape and fire detection (ie smoke alarms) within at least a sample of the flats. Within the flats, the inspection is non-destructive, but the fire resistance of doors to rooms is considered.

Measures to prevent fire are not considered unless (eg in the case of maintenance of the electrical and heating installations) the measures are within the control of, for example, the landlord.

A Type 3 fire risk assessment may sometimes be appropriate for rented flats if there is reason to suspect serious risk to residents in the event of a fire in their flats. (This might be, for example, because of the age of the block or reason for suspicion of widespread unauthorised material alterations). This type of fire risk assessment will not be possible in the case of long leasehold flats, as there is normally no right of access for freeholders.

Client	ISHA
Use	Purpose-built, self-contained flats
Number of floors - ground and above	4
Number of floors - below ground	0
Number of flats	5
Number of stair cores	1

 Approach to flats
 • Direct from stair

 Approximate period of construction
 Pre 1900

 Is the top occupied storey over 18 metres above access level?
 No

Construction details

A building of four floors (three upper floors and a lower ground floor), of brick and timber construction containing 5 converted, self contained flats.

There is a single central steel staircase serving all floors.

There is a rear door on the lower ground floor which accesses a rear garden, however, this does not provide a route to ultimate safety.



Rear face of the building - brick section, and a rendered section External wall details



Front face - brick walls

The front face of the building is brick and mortar walls. The rear of the building has a part brick section and a part rendered section. It was not possible within the scope of this fire risk assessment to categorically confirm the substrate into which this render is applied, however it appears to be render over the original brick construction.

Attention is drawn to the Ministry of Housing, Communities & Local Government Consolidated Advice Note for building owners of multi-storey, multi-occupied residential buildings, dated January 2020 (https://www.gov.uk/government/publications/buildingsafety-advice-for-building-owners-including-fire-doors) (the "Advice Note").

The Advice Note recommends that building owners should consider the risk of external fire spread as part of the fire risk assessment for multi-occupied residential buildings.

Consideration has been given to this matter within this fire risk assessment. The Advice Note further recommends the assessment of the fire risks of any external wall system, irrespective of the height of the building.

Are there any private balconies?

No

People

Are there any people especially at risk from fire?

Not Known

Fire Risk Assessment 92-94 Graham Rd Version 5

Fire Prevention

Electrical

Are electrical installations and appliances free from any obvious defect?	Yes
Are fixed installations periodically inspected and tested?	Not Known
Are portable electrical appliances used?	No

Comments

Although fixed electrical installations appear to be free from damage, there are no records available and there are no test labels affixed to installations.

Ensure fixed electrical installations are subject to a five yearly test in accordance with BS 7671.

VERSION 2: Fire Safety documentation for the testing and maintenance of fixed electrical installations is held centrally at the ISHA Head Office. The ISHA Neighbourhood Officer has confirmed that these are up to date.

Gas

Are gas installations and appliances free from any obvious defect?	N/A
Is gas equipment protected/located so as not to be prone to accidental damage?	N/A

Comments

Gas meters are located externally and not in any common area. However, the gas cupboards are open and unsecured and it is advised that these are secured to prevent tampering or accidental damage to gas installations.

Heating

Are fixed heating installations free from any obvious defect?	N/A
Are portable heaters used?	No
Comments	

There is no heating provision in the common areas.

Cooking

Does cooking take place on the premises?	No
Comments	
Cooking does not take place in the common areas.	
Arson	
Is security against arson reasonable?	Yes
Is there a reasonable absence of external fuels and ignition sources?	Yes
Comments	

Access to building via a secured main entrance door, however, this door was found to be ajar when entering the building for this inspection and it is evident the locking mechanism is defective.

Housekeeping

Is accumulation of combustibles or waste avoided?	No	
Are there appropriate storage facilities for combustible & hazardous materials?	N/A	
Comments		
There are combustibles in escape routes which should be removed. This was identified in previous FRAs.		
Building Works		
Are there any hot works being carried-out at this time?	No	

Are the premises free of any obvious signs of incorrect hot work procedures in the past?

Yes

Smoking

Are there suitable arrangements taken to prevent fires caused by smoking?

Yes

No

No

Comments

"No Smoking" signage is provided and there is no evidence of smoking taking place in the common parts.



"No Smoking" signage is provided

Dangerous Substances

Are dangerous substances present, or liable to be present?

Lightning

Is a lightning protection system installed?

Comments

There is no lightning protection visible, However, if there is lightening protection in place it should be periodically inspected by a competent person, to the frequency recommended in BS EN 62305.

Escape Routes & Fire Spread

Ease of Use



No specific occupancy risk identified. Tenants are a typical cross section of public and would include visitors and contractors. It is assumed occupants are capable of using the means of escape, unaided to reach a place of ultimate safety.

There are a number of bikes being stored on common escape routes. This was also identified in previous FRAs.



Electromagnetic door release, with additional emergency door release


Dimensions

Are travel distances reasonable?

Is there sufficient exit capacity?

Yes
Yes

Fire Doors



Comments

As part of this Type 3 Fire Risk Assessment, access was gained into a sample flat to assess the suitability of flat entrance doors, and any internal doors which open onto the entrance hallway.

Access was gained into flat 4 which has an entrance door fitted to FD30S SC standard.

The remainder of flat front doors within the building could not be assessed due to access. However, these all appear to be of the same age, condition and design of those which were accessed and were probably all installed at the same time. It is therefore reasonable to assume that they are of the same fire resisting standard.

The provision and condition of self closing devices, intumescent strips/cold smoke seals, and effective door closing action of these doors however could not be assessed and this should be confirmed ensure all doors afford FD30S SC standard of fire resistance.

The electrical cupboard should have intumescent strips and cold smoke seals fitted, and should be kept locked shut.



Example of flat entrance door. All doors of similar design and condition.



Example of externally fitted self closing device fitted to all flat doors



Example of door stops on all flat entrance doors.

Fire Risk Assessment 92-94 Graham Rd Version 5

Construction & Glazing

Are escape routes protected with suitable walls and floors?	Yes
Is there adequate compartmentation?	No
Is there reasonable limitation of linings that might promote fire spread?	Yes
Glazing which is expected to be fire resisting, inc vision panels and fanlights:	• None
Is glazing reasonable and free from any obvious defects?	Yes
Comments	

It is evident in the electrical cupboard there are numerous penetrations which are not fire stopped. The cabling appears to be carried through the building via boxed-in sections, and it cannot be confirmed if these are fire stopped where they enter flats.

These penetrations should be fire stopped within the electrical cupboard.

Given the presence of other services being carried through the building common areas such as water, without fire stopping installed, it is recommended that a full compartmentation survey is carried out in this building

VERSION 3: These tasks, generated in the previous FRA, has not been completed and therefore remains as "identified" within this FRA, and the recommended remedial work should be carried out accordingly.



Example of boxed in services in the building, affording no fire resistance



Example of boxed in services in the building, affording no fire resistance



Example of boxed in services in the building, affording no fire resistance



It was not possible to access this door

Fire Risk Assessment 92-94 Graham Rd Version 5

Dampers, Ducts & Chutes

Are there suitable measures to restrict fire spread via ducts and concealed spaces?	Yes
Comments	
No dampers ducts or chutes evident.	
Smoke Ventilation	
Areas where smoke ventilation is expected:	• Staircases
Staircases	 Openable Windows Natural Vent - Manual
Is smoke ventilation reasonable and free from any obvious defects?	Minor Defects

Comments

The break glass cover on the smoke vent control in the entrance hallway requires replacing to prevent future misuse of the ventilation system.

The electrical junction box and associated conduit is detached and broken, adjacent to the actual roof vent. This should be repaired to ensure it does not obstruct the action of the roof vent, and to ensure the circuitry is not damaged.



Smoke vent panel - with no evidence of maintenance since 2019



Smoke ventilation system maintenance label posted on control panel

Detection & Warning

Control Equipment

Is an electrical fire alarm system expected?	No
Why not?	Converted flats of stay-put standard
Is a fire detection and/or alarm system provided?	No
Is the control equipment suitably located?	N/A
Is the control equipment free from any obvious fault or defect?	N/A
Manual Fire Alarms	
Are there sufficient means of manually raising an alarm?	N/A
Are manual callpoints appropriately located and free from obvious defect?	N/A
Automatic Fire Detection	
Is there sufficient provision of automatic fire detection?	N/A
Is the type of automatic fire detection suitable and free from obvious defect?	N/A

Comments

As part of this Type 3 Fire Risk Assessment access was gained into a sample flat to assess the provision and suitability of fire alarms.

Access was gained into flat 4 which has a fire alarm provided to BS5839-6 LD 3 standard. It was noted that the fire alarm in the entrance hallway was giving a fault sound possibly indicating the backup battery requires attention.

It is always recommended as best practice to ensure that working smoke alarms are provided in all dwellings at least to a BS 5839-6 Category LD3 standard. These should ideally be Grade D alarms (mains powered with integral battery back-up), although Grade F alarms (battery powered only) are a reasonable short term measure.

VERSION 4: Access was gained into flat 4, where it was noted that the fire alarm provided within this flat is still defective and has not been repaired. It is imperative that working smoke alarms are provided within flats.

Fire Risk Assessment 92-94 Graham Rd Version 5

Audibility

Are there adequate means of alerting all relevant persons?

N/A

Fire Risk Assessment 92-94 Graham Rd Version 5

Firefighting

Fire Extinguishers

Are fire extinguishers expected?	No
Why not?	Not practicable to train residentsFire unlikely in communal areasVandalism concerns
Are fire extinguishers provided?	No
Is the provision of fire extinguishers reasonable?	Yes
Fixed Systems	
Are any fixed systems provided?	No
Is provision of fixed systems reasonable?	Yes
Fire Service Facilities	
Are any fire service facilities provided?	Yes
Types of facility	• Smoke ventilation
Is provision of fire service facilities reasonable?	Yes

Lighting

Normal Lighting

Is there adequate lighting of internal escape routes?	Yes
Is there adequate lighting of external escape routes?	N/A
Is there adequate lighting in risk critical areas?	N/A

Emergency Lighting

Method of emergency lighting of internal escape routes:	• Maintained emergency lighting (local)
Is this provision reasonable?	Yes
Method of emergency lighting of external escape routes:	• Borrowed light
Is this provision reasonable?	Yes
Method of emergency lighting of other areas:	• Not applicable
Is this provision reasonable?	Yes

Comments

Although this inspection took place during daylight hours, given the provision of street lighting in the immediate vicinity and lighting provided by surrounding buildings, it is reasonable to assume there would be sufficient borrowed light to aid escape in these areas.

Signs & Notices

Escape Routes




Comments

Provide escape signage on lobby door on the ground floor. It is indistinguishable from the adjacent flat entrance doors and therefore should be clearly identified as the escape route for escaping persons in the event of a fire.



Fire Doors



Comments

Provide Fire Door Keep Locked Shut signs on the electrical cupboard door, lower ground floor.

Other Signs & Notices

Is there suitable signage for fire service facilities?	Yes
Are fire action notices suitable?	No
Are there suitable notices for fire extinguishers?	N/A
Is there suitable zone information for the fire alarm system?	N/A

Comments

Provide fire action notices which accurately reflects the evacuation policy in place and confirm the correct action to take in the event of fire.

The fire action notice provided gives instruction for a simultaneous evacuation policy and not a stay put policy which is the correct policy for this building.

NB: This task has not been completed and is outstanding from previous FRAs



Incorrect fire action notice

Fire Safety Management

Procedures & Arrangements

Current evacuation policy

Stay Put

Further details

National Guidance for a building of this type would recommend a stay put policy is adopted. However, the Fire Action Notice gives instruction for a simultaneous evacuation policy. This should be removed and replaced with one giving the correct instruction for a stay put policy.

Are fire action procedures suitable and appropriately documented?	Not Known
Are there suitable arrangements for calling the fire service?	N/A
Is there a suitable fire assembly point?	N/A
Are there suitable arrangements for the evacuation of disabled people?	Yes

Comments

Fire Safety documentation for the testing and maintenance of fire safety systems is held centrally at the ISHA Head Office. The ISHA Neighbourhood Officer has confirmed that these are up to date.

Training & Drills



Comments

It should be ensured that employees from outside organisations are given information on the action to take in the event of fire.

The provided Fire Action Notice is incorrect.

Testing & Maintenance

Was testing & maintenance information available?	No
Are fire extinguishers subject to suitable test & maintenance?	N/A

Comments

Fire Safety documentation for the testing and maintenance of fire safety systems is held centrally at the ISHA Head Office. The ISHA Neighbourhood Officer has confirmed that these are up to date.

Record Keeping

Were fire safety records available?

No

Comments

Fire Safety documentation for the testing and maintenance of fire safety systems is held centrally at the ISHA Head Office. The ISHA Neighbourhood Officer has confirmed that these are up to date.

Tasks

Task 1

Source Version	1
Category	Escape Routes & Fire Spread
Sub Category	Ease of Use
Action Required	Bikes should not be stored as to obstruct escape routes.
	This has been identified in previous FRAs
	22/08/23 This task is still outstanding.
Priority	Medium
Status	Identified
Owner	Neighbourhood Services
Due Date	26 February 2019



Source Version	3	
Category	Signs & Notices	
Sub Category	Escape Route Signage	4
Action Required	Provide escape signage on lobby door on the ground floor. It is indistinguishable from the adjacent flat entrance doors and therefore should be clearly identified as the escape route for escaping persons in the event of a fire. 22/08/23 This task is still outstanding	
Priority	Medium	
Status	Identified	
Owner	Neighbourhood Services	
Due Date	24 March 2021	

Source Version	2
Category	Escape Routes & Fire Spread
Sub Category	Smoke Ventilation
Action Required	The roof vent at the head of the stairs was found to be open at the time of this inspection. This has probable been opened via a manual vent actuator by a resident. These were found to be insecure and require repair/replacement to ensure this fire safety system is not abused. VERSION 4: This vent was closed at the time of this inspection, however, the "break glass" cover over the smoke vent control in the entrance hallway still requires repair to prevent future misuse.
	22/08/23 The roof vent at the head of the stairs was found to be closed but the break "glass cover" still requires repair so this task is still outstanding.
Priority	Low
Status	Identified
Owner	Customer Homes
Due Date	4 September 2021

Source Version	2	
Category	Escape Routes & Fire Spread	
Sub Category	Construction and Glazing	
Action Required	Given the presence of other services being carried through the building common areas such as water, without fire stopping installed, it is recommended that a full compartmentation survey is carried out in this building	
	22/08/23 This task is still outstanding	
Priority	Advisory	
Status	Identified	
Owner	Customer Homes	
Due Date	4 September 2022	



Source Version	2	
Category	Escape Routes & Fire Spread	
Sub Category	Construction and Glazing	
Action Required	Provide fire stopping around cable penetrations in the following locations:	
	It is evident in the electrical cupboard there are numerous penetrations which are not fire stopped. The cabling appears to be carried through the building via boxed-in sections, and it cannot be confirmed if these are fire stopped where they enter flats. These penetrations should be fire stopped within the electrical cupboard. NB: This has been identified in previous FRAs 22/08/23 This task is still outstanding	
Priority	Medium	
Status	Identified	
Owner	Customer Homes	
Due Date	4 September 2020	

Source Version	1	
Category	Signs & Notices	
Sub Category	Other Signage	
Action Required	Provide fire action notice Provide fire action notices which accurately reflects the evacuation policy in place and confirm the correct action to take in the event of fire.	
	The fire action notice provided gives instruction for a simultaneous evacuation policy and not a stay put policy which is the correct policy for this building. s which confirm the action to take in the event of fire.	
	NB: This has been identified in previous FRAs	
	22/08/23 This task is still outstanding	
Priority	Medium	
Status	Identified	
Owner	Neighbourhood Services	
Due Date	26 February 2019	



Source Version	1	
Category	Fire Management	
Sub Category	Training & Drills	
Action Required	It should be ensured that employees from outside organisations are given information on the action to take in the event of fire.	
	Note - the current fire action notice is incorrect.	
	NB: This has been identified in previous FRAs	
	22/08/23 This task is still outstanding	
Priority	Medium	
Status	Identified	
Owner	Neighbourhood Services	
Due Date	26 February 2019	

Source Version	1	
Category	Escape Routes & Fire Spread	
Sub Category	Fire Doors	
Action Required	red Confirm that flat front doors, inspection of which was not possible, are to an FD30S self-closing standard.	
	Flat entrance doors within the building could not be assessed due to access. However, these all appear to be of the same age, condition and design and were probably installed at the same time. The doors appear to be solid with at least 25mm door stops. There are externally fitted self closing devices fitted to all doors, which all appear to be in good condition, are connected to the doors with no visible damage.	
	The provision and condition of intumescent strips/cold smoke seals, and effective door closing action of these doors however could not be assessed and this should be confirmed ensure all doors afford FD30S SC standard of fire resistance.	
	22/08/23	
	It was not possible to gain access to any entrance door to flats so this task is still outstanding	
Priority	Low	
Status	Identified	
Owner	Customer Homes	
Due Date	4 December 2019	

Source Version	1	
Category	Escape Routes & Fire Spread	
Sub Category	Fire Doors	
Action Required	The following doors should be kept locked shut:	
	Electrical cupboard.	
	NB: This has been identified in previous FRAs	
	22/08/23 This task is still outstanding	
Priority	Low	
Status	Identified	
Owner	Neighbourhood Services	
Due Date	4 December 2019	

Source Version	1	
Category	Escape Routes & Fire Spread	
Sub Category	Fire Doors	
Action Required	Install intumescent strips and smoke seals on the following doors:	
	Electrical cupboard, lower ground floor.	
	NB: This has been identified in previous FRAs	
	22/08/23	
	This task is still outstanding	
Priority	Medium	
Status	Identified	
Owner	Customer Homes	
Due Date	26 February 2019	



Source Version	1	
Category	Signs & Notices	
Sub Category	Fire Door Signage	
Action Required	Provide Fire Door Keep Locked Shut signs on the following doors:	
	Electrical cupboard, lower ground floor.	
	NB: This has been identified in previous FRAs	
	22/08/23	
	This task is still outstanding	
Priority	Low	
Status	Identified	
Owner	Neighbourhood Services	
Due Date	3 December 2020	



Risk Score

Risk Score

Next Assessment Due

Moderate Risk

22 August 2024

Likelihood		Potential Consequence		
	Slight Harm	Moderate Harm	Extreme Harm	
High	Moderate	Substantial	Intolerable	
Medium	Tolerable	Moderate	Substantial	
Low	Trivial	Tolerable	Moderate	
Likelihood				
Low	Unusually low likelihood of fire as	Unusually low likelihood of fire as a result of negligible potential sources of ignition.		
Medium		rmal fire hazards (e.g. potential ignition sources) for this type of occupancy, with fire hazards nerally subject to appropriate controls (other than minor shortcomings).		
High	* **	ack of adequate controls applied to one or more significant fire hazards, such as to result in gnificant increase in likelihood of fire.		
Consequence				
Slight	Outbreak of fire unlikely to result in serious injury or death of any occupant (other than an occupant sleeping in a room in which a fire occurs).			
Moderate	-	break of fire could foreseeably result in injury (including serious injury) of one or more upants, but it is unlikely to involve multiple fatalities.		
Extreme	Significant potential for serious inj	nificant potential for serious injury or death of one or more occupants.		