

Fire Risk Assessment 10 Stock Orchard Crescent Version 4

26 September 2024



Next Assessment Due: 30 September 2025 Risk Score: Moderate Risk Assessor: Jacob Troth

Contents

1 A	Action Plan Summary	3
2 I	Introduction	6
3 E	Executive Summary	7
4 F	Premises Details	8
5 F	Fire Prevention	10
6 E	Escape Routes & Fire Spread	13
7 I	Detection & Warning	17
8 F	Firefighting	19
	Lighting	
10	Signs & Notices	21
	Fire Safety Management	
12	Tasks	24
13	Risk Score	27

Action Plan Summary

Task No	. Category	Sub Category	Action Required	Priority	Status	Action Taken	Date Completed
1	Fire Prevention	Housekeeping	The storage of combustible items in electrical cupboards is excessive and should be reduced.	Medium	Identified		
			VERSION 2: Task not completed				
			12/10/2023 This task remains outstanding.				
			Version 4, 26/09/2024 Combustibles remain in communal areas. Electrical cupboard is still full of combustibles. This task remains outstanding.				
2	Fire Prevention	Smoking	No Smoking signage should be provided in the communal areas.	Low	Identified		
			VERSION 2: Task not completed				
			12/10/2023 This task remains outstanding.				
			Version 4, 26/09/2024 This task remains outstanding.				

Detection & Warning	Automatic Fire Detection	The Simultaneous Evacuation philosophy is not incorrect, but requires management consideration. If the common fire alarm system (currently defective) should be considered for replacement or significant cost of remedial work there is value in reviewing the evacuation strategy. Following a Type 4 FRA, a decision may be taken to remove the common fire alarm and revert to a Stay Put philosophy.	Advisory	Identified
		If this approach is adopted then it is recommended that the fire alarm is upgraded to the LACoRS Fire detection and alarm system recommendations; Three-or four- storey building converted into self-contained flats, which is:		
		 A mixed system Grade A: LD2 coverage in the common areas and a heat alarm in each flat in the room/lobby opening onto the escape route (interlinked); and Grade D: LD3 coverage in each flat (non- interlinked smoke alarm in the room/lobby opening onto the escape route) to protect the sleeping occupants of the flat (This is subject to the fire separation recommendations as given in LACoRS) 		
		12/10/2023 This task remains outstanding.		
		Version 4, 26/09/2024 This task remains outstanding.		

3

4	Signs & Notices	Other Signage	Provide fire action notices which confirm the action to take in the event of fire.	Medium	Identified
			VERSION 2: Task not completed		
			12/10/2023 This task remains outstanding.		
			Version 4, 26/09/2024 This task remains outstanding.		
5	Escape Routes & Fire Spread	Ease of Use	Although the amount of items currently in escape routes is not unreasonable, routes should be monitored to ensure that a build-up of items does not impede escape.	Low	Identified
			VERSION 2: Task not completed		
			12/10/2023 This task remains outstanding.		
			Version 4, 26/09/2024 This task remains outstanding.		

Introduction

This report presents the findings of a fire risk assessment carried-out at the premises by QFSM Ltd. The scope, format and limitations of the fire risk assessment have been discussed and agreed with the client.

The scope of the assessment does not include individual dwellings. Notwithstanding any statement or recommendation made with respect to smoke/heat alarms within dwellings, it is always recommended as best practice to ensure that working smoke alarms are provided in all dwellings at least to a BS 5839-6 Category LD3 standard. These should ideally be Grade D1 alarms (mains powered with integral tamper proof battery back-up), although Grade F1 alarms (integral tamper proof battery powered only) are a reasonable short term measure.

The report includes an action plan which contains recommended tasks, each with a suggested due date. These due dates are only our suggestions, and may or may not be appropriate, depending on individual circumstances such as financial constraints and requirements of enforcing authorities.

The premises risk score was assessed at the time of the fire risk assessment, and a recommended review date has been provided. The actual level of risk may change over time, as a result of tasks being completed, or new risks arising. Regardless of the review date, the fire risk assessment should be reviewed regularly so as to keep it up to date and particularly if:

- there is reason to suspect that the fire risk assessment is no longer valid; or
- there has been a significant change in the matters to which the fire risk assessment relates.

If you have any queries please contact QFSM Ltd at office@qfsmltd.co.uk.

Executive Summary

The previous FRA for this building was reviewed prior to this inspection, paying particular attention to any tasks generated by that FRA. During this inspection these tasks were inspected where access was possible, to ascertain if the recommended remedial work had been completed, and comments regarding the progress of any remedial work made accordingly. It was noted that there remains a number of tasks outstanding from the previous FRA which detail recommended remedial work required to ensure the safety of the building and that it is compliant with relative fire safety regulations and guidance. It is imperative that such remedial work is carried out within the recommended time frames given.

This new version was created on 26/09/2024 and is not a review of the fire risk assessment. This is purely an on-site audit carried out at the request of the client to ascertain the progress of any action carried out against previous tasks identified in previous versions of this fire risk assessment.

The storage of combustible items in electrical cupboards is excessive and should be reduced.

No Smoking signage should be provided in the communal areas.

There is no Fire Action Notice provided. It is imperative that residents and visitors are given clear instructions as to the action they should take in the event of a fire.

The Simultaneous Evacuation philosophy is not incorrect, but requires management consideration. If the common fire alarm system (currently defective) should be considered for replacement or significant cost of remedial work there is value in reviewing the evacuation strategy. Following a Type 4 FRA, a decision may be taken to remove the common fire alarm and revert to a Stay Put philosophy.

If this approach is adopted then it is recommended that the fire alarm is upgraded to the LACoRS Fire detection and alarm system recommendations; Three-or four-storey building converted into self-contained flats, which is:

A mixed system

• Grade A: LD2 coverage in the common areas and a heat alarm in each flat in the room/lobby opening onto the escape route (interlinked); and

• Grade D: LD3 coverage in each flat (non-interlinked smoke alarm in the room/lobby opening onto the escape route) to protect the sleeping occupants of the flat

(This is subject to the fire separation recommendations as given in LACoRS)

Although the amount of items currently in escape routes is not unreasonable, routes should be monitored to ensure that a build-up of items does not impede escape.

Giving consideration to the general fire safety arrangements within the building, and the tasks recommended as detailed within this report, it is assessed that this building presents a moderate risk.

Premises Details

Address line 1	10 Stock Orchard Crescent
Town	Islington
Postcode	N7 9SL
FRA Type	Type 1 - Common parts only (non-

destructive)

Description

A Type 1 fire risk assessment has been conducted at this building. This means the inspection of the building has been nondestructive. As well as considering the arrangements for means of escape, the fire risk assessment has included, where possible, the examination of a sample of flat entrance doors. It has also considered, so far as reasonably practicable, the separating construction between the flats and the common parts without any intrusive examination of construction. This Type of fire risk assessment has not involved entry to flats beyond the area of the flat entrance door.

Client	ISHA
Building Information	
Use	Converted, self-contained flats
Number of floors - ground and above	4
Number of floors - below ground	0
Number of flats	3
Number of stair cores	0
Approach to flats	Direct external accessEntrance hallway

External walls, front elevation External wall details

Are there any private balconies?

People

Are there any people especially at risk from fire?

Fire Risk Assessment 10 Stock Orchard Crescent Version 4

Is the top occupied storey over 18 metres above access level?

Cor	istruct	ion	details			

Traditional wall construction (rendered) with intermediate timber floors and a covered pitched roof.

Access to common area via secure door entry system with flats B & C accessed directly from the small ground floor hallway.

Flat A has direct external access and appears to cover the basement level. Electrical & gas meter cupboards located externally underneath the stoop leading to the main entrance door.

External walls, end elevation



External walls, rear elevation

Not Known

No

Approximate period of construction






The building is semi detached, with the rear and end elevation being constructed of the original brickwork with no additional external wall systems fitted. The front elevation is rendered, which appears to be applied directly to the original wall surface.

No

Pre 1900

Fire Prevention

Electrical



Comments

Gas

Documentation regarding the testing and maintenance of fixed electrical installations is held centrally by ISHA. The Neighbourhood Officer has confirmed these are all up to date.

There is a 4-gang extension lead in use in the common area, being supplied from on of the flats. It appears this lead powers an external cctv camera which has been installed. The use of such leads is unacceptable in the common area and should power be required to the CCTV camera then this should be provided adhering to the appropriate electrical regulations.

Are gas installations and appliances free from any obvious defect? Yes Is gas equipment protected/located so as not to be prone to accidental damage? Yes Comments There is no gas provision or equipment in the common areas. Heating Are fixed heating installations free from any obvious defect? N/A Are portable heaters used? No Comments There is no heating provision in the common areas. Cooking Does cooking take place on the premises? No Comments Cooking takes place within flats only and does not take place in the common parts. Fire Risk Assessment 10 Stock Orchard Crescent

Version 4


Is security against arson reasonable?	Yes
Is there a reasonable absence of external fuels and ignition sources?	Yes

Comments

Access was gained into this building via a secured main entrance door. The main entrance door was found to be locked and secure, preventing unauthorised access.

Areas immediately around the external curtilage of the building were noted as having a build up of combustibles and rubbish.

Housekeeping



Comments

The storage of combustible items in communal areas is excessive and should be reduced.

There were some items in the common entrance hallway which should be removed.

The electrical and gas meter cupboards are located externally. Whilst not affecting the common parts of the building it is always advisable to prohibit the storage of combustible items in such areas as they are directly beneath the building.

Building Works

Are there any hot works being carried-out at this time?	No
Are the premises free of any obvious signs of incorrect hot work procedures in the past?	Yes
Smoking	
Are there suitable arrangements taken to prevent fires caused by smoking?	No
Comments "No Smoking" signage should be provided in the communal areas.	

Dangerous Substances

Are dangerous substances present, or liable to be present?

Lightning

Is a lightning protection system installed?

Comments


There is no lightning protection visible, However, if there is lightening protection in place it should be periodically inspected by a competent person, to the frequency recommended in BS EN 62305.

No

No

Escape Routes & Fire Spread

Ease of Use



Comments

The provision of thumb turn devices on final exits means the doors can be opened without the use of a key, however it should be confirmed the lock has been disabled to ensure this door cannot be locked by a key.

Tenants are presumed to be a typical cross section of the public and could include visitors and contractors. It is assumed that all occupants and visitors are capable of using the means of escape unaided to reach a place of ultimate safety.

There are a small number of items located in the common areas, which whilst currently do not present a significant risk, these areas should be monitored to ensure they do not build up.


Dimensions

Are travel distances reasonable?

Is there sufficient exit capacity?

Yes

Fire Doors



Comments

It is understood that communal doors are inspected regularly by neighbourhood officers and formally recorded in the quarterly/6 monthly estate inspections with residents. Records are held with the neighbourhood officers. Flat entrance doors are inspected during the annual LGSR visits where the gas engineers record on their PDA if a door closer exists and intumescent strips and cold smoke seals exist.

The flat entrance doors within the building could not be assessed due to access within the scope of this Type 1 Fire Risk Assessment. However from external examination only, the flat entrance doors appear to be flush timber original doors, in good condition and appear to be recently installed. It is reasonable to assume these doors would provide a notional 30 minutes fire resistance. Both the flat entrance doors appear to be of the same age, condition and design and were probably all installed at the same time. It is therefore reasonable to assume that they are of the same FD30 (notional) fire resisting standard. The provision and condition of self closing devices, intumescent strips/cold smoke seals, and effective door closing action of these doors however could not be assessed and this should be confirmed ensure all doors afford FD30SC standard of fire resistance.


The flat entrance door on the right hand side opens out onto the common area. This may be the only option due to the layout of the staircase inside of the flat entrance. However, this does raise the risk of the door not being able to be fully opened if there is any obstructions in the common area immediately outside of the flat (as was the case at the time of the inspection). It is therefore imperative that the common area is clear of combustibles at all times, and it is recommended to review the layout of this flat entrance.

VERSION 2: A tenant granted access into the common area, but not into their flat. External observations of flat entrance doors draw the same conclusion as to their fire resistance as noted in the previous FRA.





Flat entrance door



No Dampers, Ducts or Chutes evident.

Fire Risk Assessment 10 Stock Orchard Crescent Version 4

Smoke Ventilation

Areas where smoke ventilation is expected:	• None
Is smoke ventilation reasonable and free from any obvious defects?	Yes
Commente	

Comments

A common fire alarm has been provided indicating a simultaneous evacuation policy is in place. However, this alarm is currently in a defective condition. Please see comments and tasks in the Detection and Warning section of this report which gives recommendations about the provision of a suitable standard and coverage of a fire alarm expected in a building of this type, and/or consideration to remove the fire alarm and adopt a stay put policy.

Detection & Warning

Is an electrical fire alarm system expected?	No	
Why not?	Converted flats of stay-put standard	
Is a fire detection and/or alarm system provided?	Yes	
Areas covered	• Communal areas	
Communal Areas		
System Category	• BS 5839 Pt6 Grade D Category L3	
Cause & Effect	• Not confirmed	
Control Equipment		
Is the control equipment suitably located?	N/A	
Is the control equipment free from any obvious fault or defect?	N/A	
Manual Fire Alarms		
Are there sufficient means of manually raising an alarm?	N/A	
Are manual callpoints appropriately located and free from obvious defect?	N/A	

Automatic Fire Detection

Is there sufficient provision of automatic fire detection?	Minor Defects
Is the type of automatic fire detection suitable and free from obvious defect?	No
Comments	

This building was originally a single private dwelling converted at some point, probably before the 1980's, to form separate flats. The building regulation standards in use today were not introduced until 1991, however, some of the principles within the early editions of ADB have been applied and generally the building meets the current guidance with the exception of smoke ventilation within the staircase.

However, a BS5839 Part 6 fire alarm system has been installed, at least in the common hallway of the building, which prompts Simultaneous Evacuation rather than the more common approach of Stay Put. It could not be confirmed within the scope of this FRA whether this fire alarm extends into the flats. It was noted that the detector has been removed and is therefore currently defective. This requires repair, after given consideration to the following recommendations:

This Simultaneous Evacuation philosophy is not incorrect, but requires management consideration. If the common fire alarm system should be considered for replacement or significant cost of remedial work there is value in reviewing the evacuation strategy. Following a Type 4 FRA, a decision may be taken to remove the common fire alarm and revert to a Stay Put philosophy.

If this approach is adopted then it is recommended that the fire alarm is upgraded to the LACoRS Fire detection and alarm system recommendations; Three-or four-storey building converted into self-contained flats, which is:

A mixed system

• Grade A: LD2 coverage in the common areas and a heat alarm in each flat in the room/lobby opening onto the escape route (interlinked); and

• Grade D: LD3 coverage in each flat (non-interlinked smoke alarm in the room/lobby opening onto the escape route) to protect the sleeping occupants of the flat

(This is subject to the fire separation recommendations as given in LACoRS)

Audibility

Are there adequate means of alerting all relevant persons?

Comments

Please see comments and task generated above.

No

Firefighting

Fire Extinguishers

Are fire extinguishers expected?	No	
Why not?	 Not practicable to train residents Fire unlikely in communal areas Vandalism concerns 	
Are fire extinguishers provided?	No	
Is the provision of fire extinguishers reasonable?	Yes	
Fixed Systems		
Are any fixed systems provided?	No	
Is provision of fixed systems reasonable?	Yes	
Fire Service Facilities		
Are any fire service facilities provided?	No	
Is provision of fire service facilities reasonable?	Yes	

Lighting

Normal Lighting

Is there adequate lighting of internal escape routes?	Yes
Is there adequate lighting of external escape routes?	N/A
Is there adequate lighting in risk critical areas?	N/A

Emergency Lighting

Method of emergency lighting of internal escape routes:	• Maintained emergency lighting (local)
Is this provision reasonable?	Yes
Method of emergency lighting of external escape routes:	• Borrowed light
Is this provision reasonable?	Yes
Method of emergency lighting of other areas:	• Not applicable
Is this provision reasonable?	Yes

Comments

Although this inspection took place during daylight hours, given the provision of street lighting in the immediate vicinity and lighting provided by surrounding buildings, it is reasonable to assume there would be sufficient borrowed light to aid escape in these areas.

Signs & Notices

Escape Routes

No
e escape routes s in ordinary use
No
Yes
N/A
N/A
N/A

Other Signs & Notices

Is there suitable signage for fire service facilities?	N/A
Are fire action notices suitable?	No
Are there suitable notices for fire extinguishers?	N/A
Is there suitable zone information for the fire alarm system?	N/A

Comments

Provide fire action notices which confirm the action to take in the event of a fire.

Fire Risk Assessment 10 Stock Orchard Crescent Version 4

Fire Safety Management

Procedures & Arrangements

Current evacuation policy

Simultaneous

Further details

Please see comments in the Detection and Warning section of this report regarding the provision of a fire alarm and considerations around the suitability of a simultaneous evacuation policy.

Are fire action procedures suitable and appropriately documented?

The fire action procedures suitable and appropriately documented.	Not Known
Are there suitable arrangements for calling the fire service?	N/A
Is there a suitable fire assembly point?	N/A
Are there suitable arrangements for the evacuation of disabled people?	Yes

Comments

These are general needs flats and as such no specific occupancy risk is identified. Tenants are presumed to be a typical cross section of public and could include visitors and contractors. It is assumed that all occupants and visitors are capable of using the means of escape unaided to reach a place of ultimate safety.

Training & Drills



Comments

Fire Action notices provide sufficient information to inform persons from outside organisations of the action to take in the event of a fire alarm actuation or discovering a fire.

Testing & Maintenance

Was testing & maintenance information available?	No
Are fire extinguishers subject to suitable test & maintenance?	N/A

Comments

Fire Safety documentation for the testing and maintenance of fire safety systems is held centrally at the ISHA Head Office. The ISHA Neighbourhood Officer has confirmed that these are up to date.

Record Keeping

Were fire safety records available?

No

Comments

Fire Safety documentation for the testing and maintenance of fire safety systems is held centrally at the ISHA Head Office. The ISHA Neighbourhood Officer has confirmed that these are up to date.

Tasks

Task 1

Source Version	1	
Category	Fire Prevention	
Sub Category	Housekeeping	
Action Required	The storage of combustible items in electrical cupboards is excessive and should be reduced.	
	VERSION 2: Task not completed	
	12/10/2023 This task remains outstanding.	
	Version 4, 26/09/2024 Combustibles remain in communal areas. Electrical cupboard is still full of combustibles. This task remains outstanding.	
Priority	Medium	
Status	Identified	
Owner	Neighbourhood Services	
Due Date	15 December 2020	

Task 2

Source Version	1
Category	Fire Prevention
Sub Category	Smoking
Action Required	No Smoking signage should be provided in the communal areas.
	VERSION 2: Task not completed
	12/10/2023
	This task remains outstanding.
	Version 4, 26/09/2024
	This task remains outstanding.
Priority	Low
Status	Identified
Owner	Neighbourhood Services
Due Date	16 June 2021

Task 3

Source Version	1
Category	Detection & Warning
Sub Category	Automatic Fire Detection
Action Required	The Simultaneous Evacuation philosophy is not incorrect, but requires management consideration. If the common fire alarm system (currently defective) should be considered for replacement or significant cost of remedial work there is value in reviewing the evacuation strategy. Following a Type 4 FRA, a decision may be taken to remove the common fire alarm and revert to a Stay Put philosophy.
	If this approach is adopted then it is recommended that the fire alarm is upgraded to the LACoRS Fire detection and alarm system recommendations; Three-or four-storey building converted into self-contained flats, which is:
	 A mixed system Grade A: LD2 coverage in the common areas and a heat alarm in each flat in the room/lobby opening onto the escape route (interlinked); and Grade D: LD3 coverage in each flat (non-interlinked smoke alarm in the room/lobby opening onto the escape route) to protect the sleeping occupants of the flat (This is subject to the fire separation recommendations as given in LACoRS)
	12/10/2023 This task remains outstanding.
	Version 4, 26/09/2024 This task remains outstanding.
Priority	Advisory
Status	Identified
Owner	Customer Homes
Due Date	16 June 2022



Task 4

Source Version	1
Category	Signs & Notices
Sub Category	Other Signage
Action Required	Provide fire action notices which confirm the action to take in the event of fire.
	VERSION 2: Task not completed
	12/10/2023 This task remains outstanding.
	Version 4, 26/09/2024 This task remains outstanding.
Priority	Medium
Status	Identified
Owner	Neighbourhood Services
Due Date	15 December 2020

Task 5

Source Version	1
Category	Escape Routes & Fire Spread
Sub Category	Ease of Use
Action Required	Although the amount of items currently in escape routes is not unreasonable, routes should be monitored to ensure that a build-up of items does not impede escape. VERSION 2: Task not completed
	12/10/2023 This task remains outstanding.
	Version 4, 26/09/2024 This task remains outstanding.
Priority	Low
Status	Identified
Owner	Neighbourhood Services
Due Date	16 June 2021

Risk Score

Risk Score

Moderate Risk

Next Assessment Due

30 September 2025

Likelihood	Potential Consequence		
	Slight Harm	Moderate Harm	Extreme Harm
High	Moderate	Substantial	Intolerable
Medium	Tolerable	Moderate	Substantial
Low	Trivial	Tolerable	Moderate
Likelihood			
Low U	Unusually low likelihood of fire as a result of negligible potential sources of ignition.		
	Normal fire hazards (e.g. potential ignition sources) for this type of occupancy, with fire hazards generally subject to appropriate controls (other than minor shortcomings).		
0	Lack of adequate controls applied to one or more significant fire hazards, such as to result in significant increase in likelihood of fire.		
Consequence			
0	Outbreak of fire unlikely to result in serious injury or death of any occupant (other than an occupant sleeping in a room in which a fire occurs).		
	Outbreak of fire could foreseeably result in injury (including serious injury) of one or more occupants, but it is unlikely to involve multiple fatalities.		
Extreme Si	Significant potential for serious injury or death of one or more occupants.		