


**Fire Risk Assessment 50 Wenlock Street** Version 4

06 September 2024



Next Assessment Due: 30 September 2025 Risk Score: Tolerable Risk Assessor: Andy Harris

## Contents

1 Action Plan Summary	
2 Introduction	5
3 Executive Summary	6
4 Premises Details	7
5 Fire Prevention	10
6 Escape Routes & Fire Spread	
7 Detection & Warning	
8 Firefighting	
9 Lighting	
10 Signs & Notices	
11 Fire Safety Management	
12 Tasks	
13 Risk Score	

Action	Plan	<b>Summary</b>
--------	------	----------------

Task No	. Category	Sub Category	Action Required	Priority	Status	Action Taken	Date Completed
1	Escape Routes & Fire Spread	Construction and Glazing	Carry out an intrusive survey of the external wall system to ascertain if it meets the current government guidance. Version 4: 06/09/24 There is no evidence available on site, this information may be held centrally, this task remains outstanding.	Medium	Identified		
2	Fire Prevention	Housekeeping	The storage of combustibles in the following locations should be reduced: The ground floor electrical cupboard. Version 4: 06/09/24 This task remains outstanding.	Medium	Identified		
3	Escape Routes & Fire Spread	Fire Doors	Consider replacing the grilles in the basement doors or confirm that the existing grilles are of the intumescent type. Version 4: 06/09/24 This task remains outstanding.	Advisory	Identified		

4	Fire Management	Testing & Maintenance	Fire extinguishers have not been tested within the last 12 months and should therefore be tested without delay.	Medium	Identified
			C02 located in basement.		
			Version 4: 06/09/24 This task remains outstanding.		
5	Signs & Notices	Other Signage	It is recommended to remove this fire action notice as it may cause confusion to residents regarding the action they should take in the event of a fire.	Medium	Identified

## Introduction

This report presents the findings of a fire risk assessment carried-out at the premises by QFSM Ltd. The scope, format and limitations of the fire risk assessment have been discussed and agreed with the client.

The scope of the assessment does not include individual dwellings. Notwithstanding any statement or recommendation made with respect to smoke/heat alarms within dwellings, it is always recommended as best practice to ensure that working smoke alarms are provided in all dwellings at least to a BS 5839-6 Category LD3 standard. These should ideally be Grade D alarms (mains powered with integral battery back-up), although Grade F alarms (battery powered only) are a reasonable short term measure.

The report includes an action plan which contains recommended tasks, each with a suggested due date. These due dates are only our suggestions, and may or may not be appropriate, depending on individual circumstances such as financial constraints and requirements of enforcing authorities.

The premises risk score was assessed at the time of the fire risk assessment, and a recommended review date has been provided. The actual level of risk may change over time, as a result of tasks being completed, or new risks arising. Regardless of the review date, the fire risk assessment should be reviewed regularly so as to keep it up to date and particularly if:

• there is reason to suspect that the fire risk assessment is no longer valid; or

• there has been a significant change in the matters to which the fire risk assessment relates.

If you have any queries please contact QFSM Ltd at office@qfsmltd.co.uk.

## **Executive Summary**

#### VERSION 4: 06/09/24

The previous FRA for this building was reviewed prior to this inspection, paying particular attention to any tasks generated by that FRA. During this inspection these tasks were inspected where access was possible, to ascertain if the recommended remedial work had been completed, and comments regarding the progress of any remedial work made accordingly.

This new version was created on 06/09/2024 and is not a review of the fire risk assessment. This is purely an on-site audit carried out at the request of the client to ascertain the progress of any action carried out against previous tasks identified in previous versions of this fire risk assessment.

There is no evidence on site that an intrusive survey of the external wall system has been carried out to ascertain if it meets the current government guidance.

Consider replacing the grilles in the basement doors or confirm that the existing grilles are of the intumescent type.

Fire extinguishers have not been tested within the last 12 months and should therefore be tested without delay.

The storage of combustibles in the following locations should be reduced.

Giving consideration to the general fire safety arrangements within the building, and the tasks recommended as detailed within this report, it is assessed that this building presents a tolerable risk.

## **Premises Details**

Address line 1	50 Wenlock Street
Town	Islington
Postcode	N1 7QW
FRA Type	Type 1 - Common parts only (non-

Гуре 1 - Common parts only (nondestructive)

Description

A Type 1 fire risk assessment has been conducted at this building. This means the inspection of the building has been nondestructive. As well as considering the arrangements for means of escape, the fire risk assessment has included, where possible, the examination of a sample of flat entrance doors. It has also considered, so far as reasonably practicable, the separating construction between the flats and the common parts without any intrusive examination of construction. This Type of fire risk assessment has not involved entry to flats beyond the area of the flat entrance door.

Client	ISHA
Building Information	
Use	Purpose-built, self-contained flats
Number of floors - ground and above	6
Number of floors - below ground	1
Number of flats	20
Number of stair cores	1
Approach to flats	• Via protected lobbies / corridors

#### Approximate period of construction

Is the top occupied storey over 18 metres above access level?

Is the external cladding or facade confirmed as non combustible?

#### Further details

Five storey purpose built flats.

Construction details

A building of six floors, with brick walls and concrete floors and stairs under a flat roof.

There is a single staircase core, with flats being accessed via protected corridors.



External walls on the front (northern) elevation



External walls on the rear (southern) elevation

External wall details



Photograph showing an identified external wall system on fifth floor

The external facade is mostly brick but a partial section appears appears to be a 'Sto-render type wall system.

Also the upper floor (fifth floor) and a section of the fourth floor appears to have some form of metallic cladded external wall system fitted. It cannot be confirmed within the scope of this fire risk assessment the type and construction of this cladding nor its inner-insulating material. Also the substrate to which the render has been applied cannot be confirmed.

It is recommended to conduct an intrusive inspection of the external walls of this building to ensure they meet the requirements of the Building Regulations.

Are there any private balconies?

Yes

Private balcony details

Private balconies are of a solid construction with the concrete deck of the balconies probably being an extension of the main

Fire Risk Assessment 50 Wenlock Street Version 4



External walls on the eastern side elevation.



1990-2000

Yes

Not Known

External walls on the western side elevation

#### concrete compartment floors. Upstands are of brick/mortar construction

## People


Are there any people especially at risk from fire?

No

Fire Risk Assessment 50 Wenlock Street Version 4

## **Fire Prevention**

### Electrical



#### Comments

Documentation regarding the testing and maintenance of fixed electrical installations is held centrally by ISHA. The Neighbourhood Officer has confirmed these are all up to date.

There are electrical sockets in the common areas, presumably for use by cleaning staff. These were in good condition and showed no evidence of misuse by residents or visitors.



Are gas installations and appliances free from any obvious defect?	N/A
Is gas equipment protected/located so as not to be prone to accidental damage?	N/A

#### Comments

Gas

Gas pipe work within the building appeared in good condition, correctly identifiable and located within riser cupboards.



Evidence of gas meter inspection

Fire Risk Assessment 50 Wenlock Street Version 4

## Heating

Are fixed heating installations free from any obvious defect?	N/A
Are portable heaters used?	No
Comments	
There is no heating provision in the common areas.	
Cooking	
Does cooking take place on the premises?	No
Comments	
Cooking takes place within flats only and does not take place in the common part	rts.
Arson	
Is security against arson reasonable?	Yes
Is there a reasonable absence of external fuels and ignition sources?	Yes

#### Comments

All entrances are fob operated and there is an external fob operated bin store.

CCTV cameras are installed internally and externally. Whilst these cameras may have been installed for security purposes they also serve to reduce the risk of deliberate fire setting.



External secure bin store



CCTV cameras are provided

## Housekeeping

Is accumulation of combustibles or waste avoided?	Yes
Are there appropriate storage facilities for combustible & hazardous materials?	N/A

#### Comments

There is some combustible storage in the ground floor and basement electrical cupboards.



# Combustibles in ground floor electrical cupboard

## **Building Works**

Are there any hot works being carried-out at this time?	No
Are the premises free of any obvious signs of incorrect hot work procedures in the past?	Yes
Smoking	
Are there suitable arrangements taken to prevent fires caused by smoking?	Yes

#### Comments

"No Smoking" signage is provided, and there is no evidence of smoking taking place in the common parts.



No smoking sign

### **Dangerous Substances**

 Are dangerous substances present, or liable to be present?
 No

 Lightning
 Is a lightning protection system installed?

 Is the lightning protection system free from any obvious defect?
 Yes

 Is the lightning protection system periodically inspected?
 Not Known

#### Comments

The Electricity at Work Regulations state that Lightning Protection systems should be serviced and maintained in accordance with the recommendations of BS EN 62305 at maximum intervals of twelve months. The system, including all lightning conductors and earth grounding installations, should be visually inspected and tested by a suitably qualified electrical engineer.

## **Escape Routes & Fire Spread**


### Ease of Use

Are exits easily and immediately openable?

Do fire exits open in direction of escape where necessary?

Are escape routes unobstructed and safe to use?

Are there reasonable measures for the evacuation of disabled people?



#### Comments

There is an emergency release device on the main entrance door to the ground floor lobby. This was checked to be working during the review and it is assumed that it fails safe to open in the event of a mains failure although this could not be checked.



Stair nosings are conspicuous at changes of level



Electromagnetic door release with emergency backup at main entrance door

#### Dimensions

Are travel distances reasonable?

Is there sufficient exit capacity?

Yes
Yes

### **Fire Doors**

Doors which are expected to be fire resisting:	<ul> <li>Basement</li> <li>Electrical Cupboards</li> <li>Flats</li> <li>Risers</li> <li>Staircases</li> </ul>
Basement Doors	• FD30S self-closing
Electrical Cupboard Doors	• FD60S
Flat Doors	• FD30S self-closing
Riser Doors	• FD60S
Staircase Doors	• FD30S self-closing
Are fire doors to a suitable standard?	Minor Defects
Is there suitable provision of self-closing devices?	Yes
Is there suitable provision of hold-open devices?	N/A
Are doors kept locked where appropriate?	Yes

#### Comments

Flat 2 was accessed and the entrance door appears to be an FD30S standard with a functional self closing device.

Two of the fire doors in the basement are fitted with air flow grilles but these do not appear to be of the intumescent type.

#### VERSION 2:

Due to current government guidelines regarding the current COVID-19 pandemic, access into flats to confirm the provision and standard of fire resisting flat entrance doors was not possible. Inspection of flat entrance doors was made by external examination only, taking into account the age and condition of the doors, and where possible referring to previous FRAs where more detailed information regarding flat entrance doors and fire alarm provision may be found. All flat entrance doors appeared to be in good condition, with no obvious visible damage or defects and therefore it can reasonably assume they would afford the same level of fire resistance as found in the previous FRA.

Fire Risk Assessment 50 Wenlock Street Version 4



Missing strips and seals Construction & Glazing



Grilles in basement doors

Are escape routes protected with suitable walls and floors?	Yes	
Is there adequate compartmentation?		
	Yes	
Is there reasonable limitation of linings that might promote fire spread?		
	Yes	
Glazing which is expected to be fire resisting, inc vision panels and fanlights:		
	• Lobbies	
Lobby Glazing		
	Georgian wired	
Is glazing reasonable and free from any obvious defects?		
	Yes	

#### Comments

It is evident that a program of fire stopping has been conducted in riser cupboards in February of 2018.



Evidence of fire stopping within riser cupboards conducted in 2018

Dampers, Ducts & Chutes



Acid etching on staircase door glazing.



It was not possible to access these doors due to fob availability

Are there suitable measures to restrict fire spread via ducts and concealed spaces?

Comments

No Dampers, Ducts or Chutes evident.

Fire Risk Assessment 50 Wenlock Street Version 4 Yes

## **Smoke Ventilation**

Areas where smoke ventilation is expected:	<ul><li> Lobbies</li><li> Staircases</li></ul>
Lobbies	Natural Vent into Shaft - Automatic
Staircases	• Natural Vent - Automatic
Is smoke ventilation reasonable and free from any obvious defects?	Yes

#### Comments

There is an AOV at the top of the staircase and full height smoke vent doors in the lobbies, both are linked to smoke detectors in the common areas.



AOV

## **Detection & Warning**

Is an electrical fire alarm system expected?	No	
Why not?	Purpose-built flats	
Is a fire detection and/or alarm system provided?	Yes	
Areas covered	• Communal areas	
Communal Areas		
System Category	• BS 5839 Pt1 Category L5	
Cause & Effect	<ul><li>Sounds alarm in ancillary areas</li><li>Operates smoke ventilation</li></ul>	
Control Equipment		
Is the control equipment suitably located?	Yes	
Is the control equipment free from any obvious fault or defect?	Yes	
Comments		

The main fire alarm panel appears to be in a healthy condition.



Main fire alarm panel

## Manual Fire Alarms

Are there sufficient means of manually raising an alarm?	Yes
Are manual callpoints appropriately located and free from obvious defect?	Yes
Comments	
Manual call points are located by the main entrance door, in the basement and b	om store.
Automatic Fire Detection	
Is there sufficient provision of automatic fire detection?	Yes
Is the type of automatic fire detection suitable and free from obvious defect?	Yes
Comments	
A BS5839-6 Category LD3 fire alarm has been installed inside the flats in this b	building.
Audibility	
Are there adequate means of alerting all relevant persons?	Yes
Comments	
Combined smoke detector/sounders are located in the basement and bin store.	

## Firefighting

## **Fire Extinguishers** Are fire extinguishers expected? No Why not? • Not practicable to train residents • Fire unlikely in communal areas Are fire extinguishers provided? Yes Predominant types of fire extinguisher: • Carbon dioxide - 5kg Last test date of extinguishers: February 2012 Are fire extinguishers readily accessible? Yes Is the provision of fire extinguishers reasonable? No

#### Comments

There is a 5kg CO2 extinguisher in the basement electrical intake room which has not been tested since 2012.

## **Fixed Systems**

Are any fixed systems provided?	No
Is provision of fixed systems reasonable?	Yes

## Fire Service Facilities


Are any fire service facilities provided?	Yes
Types of facility	• Dry rising main
Is provision of fire service facilities reasonable?	Yes

#### Comments

Floor numbers are identified both within the staircase and within outside the lift



Dry riser inlet




Dry riser outlet on each landing



Floor numbers identified on each floor level

## Lighting

### Normal Lighting



#### Comments


Although this inspection took place during daylight hours, given the provision of street lighting in the immediate vicinity and lighting provided by surrounding buildings, it is reasonable to assume there would be sufficient borrowed light to aid escape in these areas.



Maintained EL within the staircase

## Signs & Notices

### **Escape Routes**






Escape route signage

### Fire Doors

Is there signage suitable for self-closing fire doors?

Is there signage suitable for locked fire doors?

Is there signage suitable for automatic fire doors?



### **Other Signs & Notices**

Is there suitable signage for fire service facilities?	Yes
Are fire action notices suitable?	No
Are there suitable notices for fire extinguishers?	N/A
Is there suitable zone information for the fire alarm system?	N/A

#### Comments

Whilst there is a fire alarm provided in the ancillary areas, throughout the remainder of the building there is no common fire alarm provided and a stay-put policy is in place. Within the main entrance there is a fire action notice posted within the noticeboard giving information and instruction for such a stay put policy. However, adjacent to this is an additional fire action notice giving information and instruction for a simultaneous evacuation strategy. It is recommended to remove this fire action notice as it may cause confusion to residents regarding the action they should take in the event of a fire.

The smoke vent doors do not need signs.



The provided fire action notice for a stay put policy.

## **Fire Safety Management**

### Procedures & Arrangements

Current evacuation policy	Stay Put
Are fire action procedures suitable and appropriately documented?	Not Known
Are there suitable arrangements for calling the fire service?	N/A
Is there a suitable fire assembly point?	N/A
Are there suitable arrangements for the evacuation of disabled people?	Yes

#### Comments

These are general needs flats and as such no specific occupancy risk is identified. Tenants are presumed to be a typical cross section of public and could include visitors and contractors. It is assumed that all occupants and visitors are capable of using the means of escape unaided to reach a place of ultimate safety.

### Training & Drills

Are staff regularly on the premises?	No
Are employees from outside organisations given appropriate fire safety information?	Yes
_	

#### Comments

Fire action notice is provided which would give employees from outside organisations information regarding action to be taken in the event of a fire.

### Testing & Maintenance

Was testing & maintenance information available?	No
Are fire extinguishers subject to suitable test & maintenance?	No

#### Comments

Fire Safety documentation for the testing and maintenance of fire safety systems is held centrally at the ISHA Head Office. The ISHA Neighbourhood Officer has confirmed that these are up to date.

The CO2 extinguisher in the basement electrical room has not been tested since 2012.



Extinguisher test date of 2012

### Record Keeping

Were fire safety records available?

No

#### Comments

Fire Safety documentation for the testing and maintenance of fire safety systems is held centrally at the ISHA Head Office. The ISHA Neighbourhood Officer has confirmed that these are up to date.

## Tasks

## Task 1

Source Version	1	
Category	Escape Routes & Fire Spread	
Sub Category	Construction and Glazing	
Action Required	Carry out an intrusive survey of the external wall system to ascertain if it meets the current government guidance.	
	Version 4: 06/09/24 There is no evidence available on site, this information may be held centrally, this task remains outstanding.	
Priority	Medium	
Status	Identified	
Owner	Customer Homes	
Due Date	24 September 2020	

## Task 2

Source Version	1
Category	Fire Prevention
Sub Category	Housekeeping
Action Required	The storage of combustibles in the following locations should be reduced:
	The ground floor electrical cupboard.
	Version 4: 06/09/24
	This task remains outstanding.
Priority	Medium
Status	Identified
Owner	Neighbourhood Services
Due Date	24 September 2020



## Task 3

Source Version	1
Category	Escape Routes & Fire Spread
Sub Category	Fire Doors
Action Required	Consider replacing the grilles in the basement doors or confirm that the existing grilles are of the intumescent type. Version 4: 06/09/24
	This task remains outstanding.
Priority	Advisory
Status	Identified
Owner	Customer Homes
Due Date	26 March 2022



## Task 4

Source Version	1	
Category	Fire Management	
Sub Category	Testing & Maintenance	
Action Required	Fire extinguishers have not been tested within the last 12 months and should therefore be tested without delay.	
	C02 located in basement.	
	Version 4: 06/09/24	
	This task remains outstanding.	
Priority	Medium	
Status	Identified	
Owner	Neighbourhood Services	
Due Date	24 September 2020	



## Task 5

Source Version	2	
Category	Signs & Notices	Fire action
Sub Category	Other Signage	Call for Fire Brigade by
Action Required	It is recommended to remove this fire action notice as it may cause confusion to residents regarding the action they should take in the event of a fire.	Image: Section 1     A section 2       Image: Section 2     A section 2
Priority	Medium	
Status	Identified	
Owner	Neighbourhood Services	
Due Date	14 September 2021	

## **Risk Score**

Risk Score

#### Tolerable Risk

Next Assessment Due

### 30 September 2025

Likelihood		Potential Consequence			
	Slight Harm	Moderate Harm	Extreme Harm		
High	Moderate	Substantial	Intolerable		
Medium	Tolerable	Moderate	Substantial		
Low	Trivial	Tolerable	Moderate		
Likelihood					
Low	Unusually low likelihood of fire as a result of negligible potential sources of ignition.				
Medium	Normal fire hazards (e.g. potential ignition sources) for this type of occupancy, with fire hazards generally subject to appropriate controls (other than minor shortcomings).				
High	Lack of adequate controls applied to one or more significant fire hazards, such as to result in significant increase in likelihood of fire.				
Consequence					
Slight	Outbreak of fire unlikely to result in serious injury or death of any occupant (other than an occupant sleeping in a room in which a fire occurs).				
Moderate	Outbreak of fire could foreseeably result in injury (including serious injury) of one or more occupants, but it is unlikely to involve multiple fatalities.				
Extreme	Significant potential for serious injury or death of one or more occupants.				