**Audit** 9 / 14 (64.29%)

07.12.2023 10:16 GMT

Neighbourhood Officer?	Gary J
Attendees?	No
Estate?	33 Provost St
External Areas Inspected	3 / 5 (60%)
Estate Grounds Maintained and cleaned?	Yes
External Lights checked & working?	Yes
Bulk Items to be cleared?  To leave bulk items until further notice.	no
Photo 1 Photo 2 Photo 3	
Play area & equipment checked?	N/A
Premises Information box checked and secure?	Yes
No information inside.	



Abandoned Vehicles?	no
Graffiti?	no
Internal Areas Inspected	3 / 5 (60%)
Internal lights checked and working?	Yes
Internal areas maintained and cleaned?	Yes
Lift phone checked?	N/A

## Communal areas clear of obstruction?

Nc

Items on second floor. This is an going issue. Items were cleared inNovember. Both flats continue to leave large amount of items outside. Will now pass this onto tenacity officer.





Photo 5

Photo 6

## Communal Repairs?

yes

Internal door to flats 2-3 not locking. To issue work order to Delta Security. .



Photo 7

Graffiti?	no
Health & Safety / Fire checks	2 / 3 (66.67%)
Meter cupboards checked for theft of earth cables?	Yes
Fire risers secured	N/A
Fire doors checked for satisfactory self-closure?	Yes
Fire signs & notices (inc lifts) in place?	Yes
Plant rooms/bike stores/cleaner cupboards checked?	Yes
Railings and balconies checked and secure?	Yes
CCTV system checked	Yes
AOV's checked and working?	Yes

AOV on second landing is faulty, been this way for a long while. Work order is with Chigwell. I will chase this up.



Photo 8

Other comments? (Write below)

No

Issues to be address for Tenancy Officer ? (ASB, Tenancy related matters) (Write in box below)

## Attached images for Tenancy Officer?

07.12.2023 10:23 GMT

## Media summary



Photo 1



Photo 3




Photo 2



Photo 4







Photo 7




Photo 6




Photo 8