Audit 11 / 15 (73.33%)

19.03.2024 10:26 GMT

2 / 4 (50%)

Neighbourhood Officer?	Gary J
Attendees?	No
Estate?	Mandarin Wharf



Photo 1

External Areas Inspected

Estate Grounds Maintained and cleaned?

External Lights checked & working?

2 strip lights inside bin room faulty.



Photo 2

Bulk Items to be cleared?

Minor bulk. To leave until further notice.





1010 3	Photo

Play area & equipment checked?	N/A
Premises Information box checked and secure?	N/A
Abandoned Vehicles?	no
Graffiti?	no

Internal Areas Inspected

5 / 6 (83.33%)

Internal lights checked and working?

Ye

Internal areas maintained and cleaned?

Photo 1 flat sign needs polishing.

Photo 2- internal door needs washing down.

Photo 3- internal walls need washing down. But does need painting.

Photo 4- lift doors need polishing.









Photo 5

Photo 6

Pho

Lift phone checked?

res

Communal areas clear of obstruction?

Yes

Communal Repairs?

Roof AOV not opening.

2photo 1- 2x faulty lights inside the bin room need repairing.

Photo 2- bin room maglock not locking.





Roof vent is not opening. This has been reported to Ventro.

Photo 9

Photo 10

Graffiti?	no
Health & Safety / Fire checks	3 / 4 (75%)
Meter cupboards checked for theft of earth cables?	Yes
Fire risers secured	Yes
Fire doors checked for satisfactory self-closure?	Yes
Fire signs & notices (inc lifts) in place?	Yes
Plant rooms/bike stores/cleaner cupboards checked?	Yes
Railings and balconies checked and secure?	Yes
CCTV system checked	Yes
AOV's checked and working?	Yes



Photo 11

Other comments? (Write below)

No

Issues to be address for Tenancy Officer ? (ASB, Tenancy related matters) (Write in box below)

Attached images for Tenancy Officer?

96

19.03.2024 10:58 GMT

Media summary



Photo 1




Photo 3



Photo 2



Photo 4





Photo 5







Photo 7

Photo 8





Photo 9




Photo 11