Audit 9 / 14 (64.29%)

07.12.2023 14:39 GMT

Neighbourhood Officer?	Gary J
Attendees?	No
Estate?	Springwell Court



Photo 1

External Areas Inspected	2 / 4 (50%)
Estate Grounds Maintained and cleaned?	Yes
External Lights checked & working?	Yes
Bulk Items to be cleared?	yes





Photo 2

Photo 3

Play area & equipment checked?	N/A
Premises Information box checked and secure?	N/A
Abandoned Vehicles?	no
Graffiti?	no
Internal Areas Inspected	3 / 6 (50%)
Internal lights checked and working?	Yes

Photo 1- Faulty light inside electrical intake cupboard - to issue work order.

Photo 2- Faulty lift light - this has already been reported. To chase repair.





Photo 4

Photo 5

Internal areas maintained and cleaned?

No

Window cills need cleaning, quite dusty.

Marks/stains on wall. Need washing down. Some marks may not come off.





Photo 6

Photo 7

Lift phone checked?	No
There is no lift phone line.	
Communal areas clear of obstruction?	Yes
Communal Repairs?	yes
Electrical cupboard faulty light.	
Graffiti?	no
Health & Safety / Fire checks	3 / 3 (100%)
Meter cupboards checked for theft of earth cables?	Yes
Fire risers secured	N/A
Fire doors checked for satisfactory self-closure?	Yes
Fire signs & notices (inc lifts) in place?	Yes
Plant rooms/bike stores/cleaner cupboards checked?	Yes
Railings and balconies checked and secure?	Yes
CCTV system checked	Yes
AOV's checked and working?	Yes
Other comments? (Write below)	Yes

Photo 1- damp patches of the top floor ceiling. To report as we do not maintain the roof.

Photo 2- plaster blown on wall by door to flats 5-7. To look into works in new year.





Photo 9

Issues to be address for Tenancy Officer ? (ASB, Tenancy related matters) (Write in box below)

Attached images for Tenancy Officer?

07.12.2023 14:54 GMT

Media summary







Photo 3



Photo 2




Photo 4








Photo 7




Photo 6



Photo 8



Photo 9