Neighbourhood Officer	Ауо А
Other Attendees?	Yes
Teslim	

Estate?	Corbet Road
External Areas Inspected - 80%	80%
Estate Grounds Maintained and cleaned?	Yes
External Lights checked & working?	Yes
Bulk Items to be cleared?	no
Play area & equipment checked?	N/A
Premises Information box checked and secure?	Yes
Abandoned Vehicles?	yes
Photo 1 Photo 2	
Graffiti?	no
Internal Areas Inspected - 66.67%	66.67%
Internal lights check and working?	Yes

75%

Internal areas maintained and cleaned?	Yes
Lift phone checked?	Yes
Communal areas clear of obstruction?	Yes
Communal Repairs?	no
Graffiti?	no
Health & Safety / Fire checks - 75%	75%
Meter cupboards check for theft of earth cables?	Yes
Fire risers secured	Yes
Fire doors checked for satisfactory self-closure?	Yes
Fire signs & notices (inc lifts) in place?	Yes
Plant rooms/bike stores/cleaner cupboards checked?	Yes
Railings and balconies checked and secure?	Yes
CCTV system checked	Yes
AOV's checked and working?	Yes
Other comments? (Write below)	No

Issues to be address for Tenancy Officer? (ASB, Tenancy related matters) (Write in box below)

Attached images for Tenancy Officer?

## Appendix






Photo 1

Photo 2