Audit - 68.75%

26.01.2023 13:17 GMT

Neighbourhood Officer?	Segun A
Attendees?	No
Estate?	Halley & Ken Wilson
External Areas Inspected - 80%	80%
Estate Grounds Maintained and cleaned?	Yes
External Lights checked & working?	Yes
Bulk Items to be cleared?	yes
NSO to report removal	





Photo 1

Photo 2

Play area & equipment checked?	N/A
Premises Information box checked and secure?	Yes
Abandoned Vehicles?	yes

Reported to Customers service team





Photo 3

Photo 4

Graffiti?	no
Internal Areas Inspected - 50%	50%

Internal lights checked and working?					Yes
Internal areas maintained and cleaned?					Yes
Lift phone checked?					Yes
Communal areas clear of obstruction? NSO have contacted residents to remove all items in communal area as a matter of urgency.				No	
Photo 5 Photo 11	Photo 6	Photo 7	Photo 8	Photo 9 Photo 15	Photo 10 Photo 16
Communal Repairs?				no	



Photo 17

Graffiti?	no
Health & Safety / Fire checks - 75%	75%
Meter cupboards checked for theft of earth cables?	Yes
Fire risers secured	Yes
Fire doors checked for satisfactory self-closure?	Yes
Fire signs & notices (inc lifts) in place?	Yes
Plant rooms/bike stores/cleaner cupboards checked?	Yes
Railings and balconies checked and secure?	Yes
CCTV system checked	Yes

AOV's checked and working?	No
Other comments? (Write below)	No
Issues to be address for Tenancy Officer ? (ASB, Tenancy related matters) (Write in box below)	
Attached images for Tenancy Officer?	



26.01.2023 14:21 GMT

Appendix



Photo 1



Photo 3



Photo 2



Photo 4




Photo 5



Photo 7



Photo 6



Photo 8



Photo 9




Photo 11




Photo 10



Photo 12




Photo 13




Photo 15




Photo 14



Photo 16



Photo 17