ISLAND APARTMENTS 29-56 30/01/2025, 15:10

Jan inspections

Thursday 30 January 2025

Prepared For Isha

20 Issues Identified



FRONT ENTRANCE (CONSTRUCTION ZONE)

Assigned To Na

Good



FIRE PANEL (SOMEONE HASN'T LOCKED IT)

Assigned To Na

Good



INTERNAL LIGHTS

Assigned To Na

Good



DECORATION AND STEEL CORNER

Assigned To Mnm

Raise wo



STEEL CORNER REQUIRED GF POSSIBLE 2.2M LONG AND DECORATION OF WALL

Assigned To Mnm

Raise wo



2M CORNER REQUIRED

Assigned To Mnm

Raise wo



NOTICE BOARD

Assigned To Magda

Magda are we to provide details there is already idm property management details



AS ABOVE

Assigned To As Above

As above



CCTV OPERATIONALAssigned To Na



Good



2M CNR AND DECORATION

Assigned To Mnm
Raise wo close to door 31 gf



FIRE ALARM TESTING

Assigned To Na Good



LIFT OPERATING

Assigned To Na Good



2 LIGHTS OUT IN LIFT Assigned To Fdh/apex Raise wo



HOLE 5TH FLOOR NEXT TO LIFTAssigned To Mnm
Raise wo



STEINS ENTIRE 5TH FLOOR Assigned To Speak To Magda Speak to Magda



5TH FLOOR LOCK CHANGE OPPOSITE LIFT FB02Assigned To Delta
Raise wo



LOCK CHANGE NEAR 38 FB02

Assigned To Delta

Raise wo



FIRE DOOR GLASS 39

Assigned To Fdh

Raise wo



CONSTRUCTION TIMETABLE

Assigned To Info

Magda



BIN CHAMBER

Assigned To Na

Good